iro///Parts

Vacuum Brake Booster Plunger Seal Kit

Part# 001 430 07085



OEM Design

ATE brake boosters found in many Mercedes and Volvo vehicles experience a worn and leaking vacuum plunger seal 03.7718-5028.1, which is characterized by a loud hissing noise and loss of braking power assist. The only option from the dealer is to purchase a complete brake booster assembly, which is exorbitantly expensive.



Problems

- Reduced power brake assistance can increase stopping distance
- Brake booster seal leakage can affect fuel injection system and other components that rely on specific vacuum levels



ÜRO Solution

ÜRO Parts has developed an exclusive and simple repair solution for this common failure. ÜRO provides a new replacement vacuum booster plunger seal, which fixes this failure much more economically than replacing the complete booster assembly.





Durable EPDM reproduction of ATE seal

03.7718-5028.1 for maximum longevity

- Brake Booster Plunger Seal Kit includes seal driver tool and silicone grease
- Easy installation (see instructional video)

Vehicle Applications

Mercedes: 2001-2015 C-Class, 2010-2013 E-Class, 2010-2013 GLK, 1998-2005 ML Volvo: 2001-2009 S60, 1999-2006 S80, 2001-2007 V70, 2003-2007 XC70

