




## Mercedes-Benz Intake Manifold Repair Kit

Part# 272 140 2401R-PRM



### OEM Design

The OEM intake manifold swirl flap actuator has a fragile plastic actuator rod, a plastic pivot lever, and a thin rubber dashpot vacuum diaphragm.



### Problems

- Pivot lever breaks, disabling system
- Misaligned actuator rod breaks
- Rubber diaphragm in dashpot tears
- Swirl flap system failure reduces power and mileage, creates engine fault codes, and can permanently damage emission control equipment



### ÜRO Solution

The ÜRO Premium Intake Manifold Repair Kit provides an upgraded vacuum actuator with a metal actuator rod, aluminum swirl flap pivot lever, and silicone dashpot diaphragm.



### Advantages

- Aluminum pivot lever with Delrin pivot bushing and receiver cups
- Aluminum actuator rod with steel-reinforced socket
- High-temperature silicone diaphragm
- Redesigned actuator stroke to prevent bottom-out on manifold stops
- Lifetime warranty

### Vehicle Applications

2005 - 2013 Mercedes-Benz with M272 V6 or M273 V8 engine