


PART NO. 858

TOLERANCES UNLESS SPECIFIED  
 TWO PLACE DECIMALS +/- .015      THREE PLACE DECIMALS +/- .005      ANGLES +/- 1°



APPLICATION - FORD REPAIR HARNESS - RADIATOR COOLING FAN MOTOR  
 REPLACES O.E.M. #F8AZ-14A411-BA, 1U2Z-14S411-ADA, WPT-168, 88988310, PT1859

NOTE: OE SUPPLIED SOLDER WIRE, BUTT SPLICES, AND INSTRUCTION SHEET ARE OPTIONAL.

					MATERIAL	N/A	SCALE	NTS			
					FINISH	N/A	DATE	10-21-10		DWN. BY	CAP
							ENGINEER	10-21-10		DGH	
							APPROVED	10-21-10		TDS	
							PURCH.	<input type="checkbox"/>		PROD.	<input type="checkbox"/>
E	REDRAWN; SEE ECN FOR DETAILS	42217	3-22-17	SAM	CAD REF.	N/A	MODEL	N/A	TITLE		PIGTAIL ASSEMBLY
L	REVISION	CN	DATE	BY					PART NO.		858