

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	color code	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
ACURA													
Acura	CSX	2008-2011			31R204	17-20204AK		3	35(4)	315MHz	Yes	TRW	42753-SNA-A83
Acura	ILX	2013-2015			31R204	17-20725AK	17-20720AK	5	71(8)	315MHz	Yes	Continental	42753-TX6-A81
Acura	ILX	2016-2018			31R204	17-20725AK	17-20720AK	5	71(8)	315MHz	Yes	Continental	42753-TZ3-A51
Acura	MDX	2004-2006			31R301	17-20036AK	17-20206AK	4/2	35(4)	315MHz	Yes	TRW	06421-S3V-A04
Acura	MDX	2007-2013			31R301		17-20216AK	1	35(4)	315MHz		Pacific	42753-STK-A04
Acura	MDX	2014-2015			31R301	17-20725AK	17-20720AK	5	71(8)	315MHz	Yes	Continental	42753-TX4-A51
Acura	MDX	2016-2018			31R301	17-20725AK	17-20720AK	5	71(8)	315MHz	Yes	Continental	42753-TZ3-A51
Acura	NSX	2017			Dealer	17-20725AK	17-20720AK	6	71(8)	315MHz	Yes	Continental	42753-T6N-A01
Acura	NSX	2018			Dealer				71(8)	433MHz	Yes	Continental	42753-TG7-A51
Acura	RDX	2007-2012			31R301		17-20216AK	1	35(4)	315MHz		Pacific	42753-STK-A04
Acura	RDX	2013-2015			31R301	17-20725AK	17-20720AK	5	71(8)	315MHz	Yes	Continental	42753-TX4-A51
Acura	RDX	2016-2018			31R301	17-20725AK	17-20720AK	5	71(8)	315MHz	Yes	Continental	42753-TZ3-A51
Acura	RL	2005-2008			31R301	17-20036AK	17-20206AK	4/2	35(4)	315MHz	Yes	TRW	06421-S3V-A04
Acura	RL	2009-2013			31R301	17-20036AK	17-20206AK	4/2	35(4)	315MHz	Yes	TRW	42753-SHJ-A53
Acura	RLX	2014-2015			31R301		17-20204AK	3	35(4)	315MHz		TRW	42753-TY2-A51
Acura	RLX	2016-2017			31R301	17-20725AK	17-20720AK	5	71(8)	315MHz	Yes	Continental	42753-TX4-A51
Acura	TL	2005-2008			31R301	17-20036AK	17-20206AK	4/2	35(4)	315MHz	Yes	TRW	06421-S3V-A04
Acura	TL	2009-2013			31R301		17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-TK4-A01
Acura	TL	2014			31R301		17-20204AK	3	35(4)	315MHz		TRW	42753-TY2-A51
Acura	TLX	2015-2018			31R301	17-20725AK	17-20720AK	5	71(8)	315MHz	Yes	Continental	42753-TZ3-A51
Acura	TSX	2007-2008			31R301		17-20216AK	1	35(4)	315MHz		Pacific	42753-STK-A02
Acura	TSX	2009-2014			31R301		17-20216AK	1	35(4)	315MHz		Pacific	42753-TL2-A52
Acura	ZDX	2010-2015			31R301		17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-TK4-A01
ALFA ROMEO													
Alfa Romeo	4C	2015-2018								433MHz	Yes	Schrader	05154876AA
Alfa Romeo	Giulia	2016-2018								433MHz	Yes	Continental	68105280AF
Alfa Romeo	Stelvio	2018								433MHz	Yes	Continental	68336101AA
ASTON MARTIN													
Aston Martin	DB9	2015	Copy Only							433MHz	Yes	HUF	224549
Aston Martin	Rapide	2015	Copy Only							433MHz	Yes	HUF	224549
Aston Martin	V12 Vanquish	2015								433MHz	Yes	HUF	7PP907275F
Aston Martin	Vanquish	2015	Copy Only							433MHz	Yes	HUF	224549
AUDI													
Audi	A1	2014	Indirect TPMS		Indirect								-
Audi	A3 & A3 Quattro	2008-2011			31R402		17-20202AK	2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Audi	A3 & A3 Quattro	2012-2018	Indirect TPMS		Indirect								-
Audi	A4 & A4 Quattro	2002-2008			31R402	17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	A4 & A4 Quattro	2009-2012			31R402		17-20202AK	2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Audi	A4 & A4 Quattro	2012-2018	Indirect TPMS		Indirect								-
Audi	A5 & A5 Quattro	2008-2012			31R402		17-20202AK	2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Audi	A5 & A5 Quattro	2012-2018	Indirect TPMS		Indirect								-
Audi	A6	2000-2003	433MHz			17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	4D0-907-275C
Audi	A6	2000-2004	315MHz			17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	315MHz	Yes	Beru	4D0-907-275D
Audi	A6	2004	433MHz			17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	A6	2005-2008			31R403	17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	A6	2009			31R403	17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	A6	2010-2012			31R403	17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	4F0-907-275D
Audi	A6	2012-2018	Indirect TPMS		Indirect								-
Audi	A6 Quattro	2006-2008				17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	A6 Quattro	2009	To Vin: 4F-9N043 000 / 4F-9Y000 220			17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	4F0-907-275B

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Audi	A6 Quattro	2009	From Vin: 4F-9N043 001 / 4F-9Y000 221		17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275D
Audi	A6 Quattro	2010-2012			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275D
Audi	A7	2012-2017	Indirect TPMS	Indirect									-
Audi	A8	2000											-
Audi	A8 Quattro	2000-2003		31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	4D0-907-275A
Audi	A8 Quattro	2004-2007		31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes		4D0-907-275
Audi	A8 Quattro	2008-2010		31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4D0-907-275C
Audi	A8 Quattro	2011-2017	Indirect TPMS	Indirect									-
Audi	Allroad	2013-2017	Indirect TPMS	Indirect									-
Audi	Allroad Quattro	2001-2005		31R403	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	4D0-907-275A
Audi	Q3	2014-2018	Indirect TPMS	Indirect									-
Audi	Q5	2008-2012		31R402		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Audi	Q5	2013-2018	Indirect TPMS	Indirect									-
Audi	Q7	2005-2009		31R402	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	Q7	2010-2018	Indirect TPMS	Indirect									-
Audi	R8	2008-2012		31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	R8	2013-2015	315MHz	31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)			Beru	7PP 907 275G
Audi	R8	2013-2017	433MHz	31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	7PP 907 275F
AUDI	R8	2018	315MHz							315MHz	Yes	HUF	7PP 907 275G
AUDI	R8	2018	433MHz							433MHz	Yes	HUF	7PP 907 275F
AUDI	RS3	2017-2018	315MHz							315MHz	Yes	HUF	5Q0 907 275C
AUDI	RS3	2017-2018	433MHz							433MHz	Yes	HUF	5Q0 907 275B
Audi	RS4	2007-2009		31R402	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	RS5	2013-2016	Indirect TPMS	Indirect									-
Audi	RS6	2003		31R402	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	4D0-907-275A
Audi	RS6	2003		31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4D0-907-275C
Audi	RS7	2014-2015	315MHz	31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)			Beru	7PP 907 275G
Audi	RS7	2014-2017	433MHz	31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	7PP 907 275F
AUDI	RS7	2018	315MHz							315MHz	Yes	HUF	7PP 907 275G
AUDI	RS7	2018	433MHz							433MHz	Yes	HUF	7PP 907 275F
Audi	S3	2014-2017	Indirect TPMS	Indirect									-
Audi	S4	2002-2009		31R402	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	S4	2010-2012		31R402		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Audi	S4	2013-2018	Indirect TPMS	Indirect									-
Audi	S5	2008-2012		31R402		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Audi	S5	2013-2018	Indirect TPMS	Indirect									-
Audi	S6	2004-2008			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Audi	S6	2009	Before May		17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Audi	S6	2009	After June		17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275D
Audi	S6	2010-2012			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275D
Audi	S6	2013-2016	Indirect TPMS	Indirect									-
Audi	S7	2013-2016	Indirect TPMS	Indirect									-
Audi	S8	2000-2007	315MHz	31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	4D0-907-275D
Audi	S8	2000-2007	433MHz	31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4D0-907-275C
Audi	S8	2008-2009		31R404	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4D0-907-275C
Audi	S8	2014-2015	Indirect TPMS	Indirect									-
Audi	S8	2016			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275D
AUDI	S8	2018	315MHz							315MHz	Yes	HUF	7PP 907 275G
AUDI	S8	2018	433MHz							433MHz	Yes	HUF	7PP 907 275F
Audi	SQ5	2014-2018			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275D
Audi	TT	2008-2012		31R402		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Audi	TT	2013-2017	Indirect TPMS	Indirect						315MHz	Yes		-
BENTLEY													
Bentley	Arnage	2008			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Bentley	Azure	2007-2010			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Bentley	Continental	2003-2005	Before May: Copy ID Only Smart Sensor		17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4D0-907-275C
Bentley	Continental	2005-2010	After June		17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Bentley	Continental	2011-2015			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275D
Bentley	Flying Spur	2006-2015			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Bentley	Mulsanne	2011-2012			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Bentley	Mulsanne	2013-2016			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275D
BMW													
BMW	1 Series	2007-2009		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	1 Series	2010	Excl 128i	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	1 Series	2010	128i Before Sept 2010	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	1 Series	2010	128i After Sept 2010	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
BMW	1 Series	2011-2014		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	2 Series	2014-2016		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BMW	2 Series	2017-2018			17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	VDO	36 10 6 881 890
BMW	3 Series	2000-2001		31R407						315MHz	Yes		36 14 2 360 419
BMW	3 Series	2002	315MHz; Before March 2002	31R407						315MHz	Yes		36 14 2 360 419
BMW	3 Series	2015-2017		31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	3 Series	2002	After February 2002; 433MHz	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 14 2 360 420
BMW	3 Series	2017-2018			17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	VDO	36 10 6 881 890
BMW	3 Series	2003		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 14 2 360 420
BMW	3 Series	2004-2006	RPA SYSTEM	31R407									
BMW	3 Series	2007-2009		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	3 Series	2010		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	3 Series	2011	Excl 335i Sedan 335i xDrive Sedan	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	3 Series	2011	335i Sedan 335i xDrive Sedan	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BMW	3 Series	2012-2013	3.0 Liter Excl 335i Sedan	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	3 Series	2012-2013	2.0 Liter + 335i Sedan with 3.0 Liter	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BMW	3 Series	2014	After February	31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	3 Series	2014	Before March	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BMW	4 Series	2014	Before March	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BMW	4 Series	2014	After February	31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	4 Series	2015-2017		31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	4 Series	2018			17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	VDO	36 10 6 881 890
BMW	5 Series	2000-2001		31R407						315MHz	Yes		36 14 2 360 419
BMW	5 Series	2002	315MHz; Before March 2002	31R407						315MHz	Yes		36 14 2 360 419
BMW	5 Series	2014-2016	535d 535d xDrive After March 2014	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BMW	5 Series	2002	After February 2002; 433MHz	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 14 2 360 420
BMW	5 Series	2017	Gran Turismo							433MHz	Yes	Huf	36 10 6 874 830
BMW	5 Series	2003-2005		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 14 2 360 420
BMW	5 Series	2017-2018								433MHz	Yes	Huf	36 10 6 876 957
BMW	5 Series	2006-2009		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	5 Series	2010	Before Sept 2010	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
BMW	5 Series	2010	After Septer 2010	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	5 Series	2011-2013		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	5 Series	2014	Excl 535d 535d xDrive	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	5 Series	2014	535d 535d xDrive Before March 2014	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	6 Series	2006-2010		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	6 Series	2012-2016		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	6 Series	2018	Grand Turismo							433MHz	Yes		36 10 6 876 957
BMW	6 Series	2017-2018								433MHz	Yes	Huf	36 10 6 874 830
BMW	7 Series	2000-2001		31R407						315MHz	Yes		36 14 2 360 419
BMW	7 Series	2002	315MHz; Before March 2002	31R407						315MHz	Yes		36 14 2 360 419
BMW	7 Series	2002	After February 2002; 433MHz	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 14 2 360 420
BMW	7 Series	2003		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 14 2 360 420
BMW	7 Series	2004-2005	RPA SYSTEM	31R407									
BMW	7 Series	2006-2009		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	7 Series	2010	Excl 750i 750i xDrive 760Li	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	7 Series	2010	750i 750i xDrive 760Li Before Sept 2010	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	7 Series	2010	750i 750i xDrive 760Li After Sept 2010	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	7 Series	2011	750i 750i xDrive 760Li	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	7 Series	2011	740i 740Li 750Li 750Li xDrive	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	7 Series	2012-2014		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	7 Series	2015	740Ld xDrive; Before July	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BMW	7 Series	2015	Exc. 740Ld xDrive	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	7 Series	2016								433MHz	Yes	Huf	36 10 6 872 803
BMW	7 Series	2017-2018								433MHz	Yes		36 10 6 876 957
BMW	Active Hybrid 3	2013-2015		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BMW	Active Hybrid 5	2012-2015		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	Active Hybrid 7	2013-2015		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	Alpina B7	2007-2008		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
BMW	Alpina B7	2011-2015		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	Alpina B7 and B7L Models (xDrive)	2011-2015		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	I3	2014-2018		31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	I8	2014-2018		31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	M235i (incl xDrive)	2014-2015		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BMW	M3	2008-2009		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	M3	2010-2012		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz		Huf	36 10 6 856 227
BMW	M3	2013		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz		Huf	36 10 6 856 227
BMW	M3	2015		31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	M4	2015		31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	M5	2006-2010		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	M5	2013-2015		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz		Huf	36 10 6 856 227
BMW	M6	2006-2010		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	M6	2012-2015		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz		Huf	36 10 6 856 227
BMW	X1	2013-2015		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	X1	2016-2017		31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	X1	2018								433MHz	Yes	VDO	36 10 6 881 890
BMW	X3	2006-2009		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	X3	2011-2015	Before November 2015	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	X3	2015 - 2017	After October 2015	31R407	17-50340, 17-50342, 17-50344, 17-50346					433MHz	Yes	Huf	36 10 6 874 830
BMW	X4	2015-2016		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	X4	2017		31R407						433MHz	Yes		36 10 6 874 830
BMW	X5	2000-2003		31R407						433MHz	Yes		36 14 6 872 887
BMW	X5	2007-2009		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	X5	2014-2017		31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	X5	2010	Before October 2010	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	X5	2018								433MHz	Yes	VDO	36 10 6 881 890
BMW	X5	2010	After October 2010	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	X5	2011-2013		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	X6	2008-2009		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	X6	2010		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
BMW	X6	2015-2017		31R407	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	36 10 6 856 209
BMW	X6	2010		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	X6	2018								433MHz	Yes	VDO	36 10 6 881 890
BMW	X6	2011-2014		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	Z4	2006-2009		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	Z4	2010	01/2010 - 09/2010	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 23 6 798 726
BMW	Z4	2010	10/2010 - 01/2011	31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	Z4	2011-2014		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 856 227
BMW	Z4	2015-2016		31R407	17-50340, 17-50342, 17-50344, 17-50346				34(6)	433MHz	Yes	Huf	36 10 6 798 872
BUGATTI													
Bugatti	Veyron	2005-2006			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)			Beru	-
BUICK													
Buick	Allure	2007-2008	Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Buick	Allure	2007-2008	Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Buick	Allure	2009		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Buick	Allure	2010		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	12768826
Buick	Cascada	2016-2018		31R105			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Buick	Enclave	2008	Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Buick	Enclave	2016-2017		31R109			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598771
Buick	Enclave	2008	Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Buick	Enclave	2018								433MHz	Yes	Schrader	13516165
Buick	Enclave	2009-2013		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Buick	Enclave	2014		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Buick	Enclave	2015		31R109			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	23445327
Buick	Encore	2013		31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20922900
Buick	Encore	2016-2017		31R105			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13589597
Buick	Encore	2018					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Buick	Encore	2014-2015		31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Buick	Envision	2017		31R118			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Buick	Lacrosse	2007	Siemens Sensor			17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Buick	Lacrosse	2016					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Buick	Lacrosse	2007	Schrader Sensor			17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Buick	Lacrosse	2017-2018					17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773
Buick	Lacrosse	2008-2009		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Buick	LaCrosse	2010-2013		31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Buick	LaCrosse	2014-2015		31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Buick	LaSabre	2007		31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25799331
Buick	LaSabre	2005		31R107			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Buick	Lucerne	2007-2011					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Buick	Rainier	2006		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25774006
Buick	Rainier	2007	Clamp-In	31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25774006
Buick	Rainier	2007	Snap-In Sensor	31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25799331
Buick	Regal	2011-2013		31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Buick	Regal	2014-2016		31R118			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Buick	Regal	2017		31R118			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Buick	Regal	2018					17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773
Buick	Verano	2012-2015		31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Buick	Verano	2016-2017		31R105			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
CADILLAC													
Cadillac	ATS	2013		31R106			17-50397		n/a	315MHz	Yes	Continental	22959744
Cadillac	ATS	2013		31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Cadillac	ATS	2013		31R106	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	22959748
Cadillac	ATS	2014-2015	Excluding Sport	31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Cadillac	ATS	2014-2015	Sport	31R106		17-20107AK		4	62(7)	315MHz	Yes	Continental	15268606
Cadillac	ATS	2016-2017	Excluding Sport	31R118			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Cadillac	ATS	2018	315MHz				17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Cadillac	ATS	2018	433MHz				17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598787
Cadillac	ATS-V	2013-2018				17-20107AK		4	62(7)	315MHz	Yes	Schrader	20964159
Cadillac	CT6	2016-2018						4	62(7)	433MHz	Yes	Schrader	13598773
Cadillac	CTS	2004-2007		31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25774006
Cadillac	CTS	2008		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615

VEHICLE INFORMATION					SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Cadillac	CTS	2009-2013	Excludes: CTS V	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Cadillac	CTS	2009-2013	Sub Model: V	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	20925924
Cadillac	CTS	2014-2015	Excludes: CTS V	31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20964159
Cadillac	CTS	2014	Sub Model: V	31R106		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Cadillac	CTS	2015-2017	Sub Model: V	31R106		17-20107AK		4	62(7)	315MHz	Yes	Schrader	20964159
Cadillac	CTS	2016-2018	Excludes: CTS V	31R106			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	20964159
Cadillac	CTS	2018	433MHz				17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598772
Cadillac	Deville	2001-2005		31R426		17-20028AK		3	62(7)	315MHz	Yes	Schrader	25773946
Cadillac	DTS	2006	w/ Clamp-In Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Cadillac	DTS	2006	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Cadillac	DTS	2007-2011		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Cadillac	ELR	2014					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Cadillac	ELR	2015					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Cadillac	ELR	2016					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Cadillac	Escalade	2004		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15136883
Cadillac	Escalade	2005-2006		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15114379
Cadillac	Escalade	2007	w/ TRW Clamp-In: before 10/06/06	31R108		17-20015AK		3	62(7)	315MHz	Yes	TRW	15825475
Cadillac	Escalade	2007	w/ Schrader Snap-In: after 10/06/06	31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Cadillac	Escalade	2008-2013		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Cadillac	Escalade	2014		31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Cadillac	Escalade	2015-2016		31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Cadillac	Escalade	2017-2018					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Cadillac	Escalade	2018	433MHz				17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773
Cadillac	Seville	2001-2004		31R426		17-20028AK		3	62(7)	315MHz	Yes	Schrader	25773946
Cadillac	SRX	2004-2006		31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25774006
Cadillac	SRX	2007-2009		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Cadillac	SRX	2010-2013		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	12768826
Cadillac	SRX	2014		31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Cadillac	SRX	2015	433MHz	31R106						433MHz	Yes	Schrader	13581561
Cadillac	SRX	2015	315MHz	31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Cadillac	SRX	2016		31R118			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Cadillac	STS	2005-2008		31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25758220
Cadillac	STS	2009	Snap-In Sensor: EXC: STS-V	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Cadillac	STS	2009	Clamp-In Sensor: STS-V	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	92186507
Cadillac	STS	2010-2011		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Cadillac	XLR	2004-2009		31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25758220
Cadillac	XTS	2017-2018					17-20045			433MHz	Yes	Schrader	13598773
Cadillac	XTS	2018	433MHz				17-20045			433MHz	Yes	Schrader	13581558
Cadillac	XTS	2013		31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20922900
Cadillac	XTS	2014		31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Cadillac	XTS	2015-2016	315MHz	31R106			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Cadillac	XTS	2017					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
CHEVROLET													
Chevrolet	Avalanche	2004		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15136883
Chevrolet	Avalanche	2005-2006		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15114379
Chevrolet	Avalanche	2007	w/ TRW Clamp-In: before 10/06/06	31R108		17-20015AK		3	62(7)	315MHz	Yes	TRW	15825475
Chevrolet	Avalanche	2007	w/ Schrader Snap-In: after 10/06/06	31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Avalanche	2008-2013		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Aveo	2007-2011	* Dealer Relearn	31R203			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Chevrolet	Bolt	2017					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Camaro	2010-2011		31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	12768826
Chevrolet	Camaro	2012-2013	Performance Package AND ZL1	31R105	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Schrader	22959748
Chevrolet	Camaro	2012-2013	Excluding: Performance Package AND ZL1	31R105				4	62(7)	315MHz	Yes	Schrader	20922900
Chevrolet	Camaro	2014	315MHz; Sub Model: ZL1	31R105		17-20107AK		4	62(7)	315MHz	Yes	Schrader	20964159
Chevrolet	Camaro	2014	315MHz; Excluding: ZL1	31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Camaro	2014	433MHz	31R105						433MHz	Yes	Schrader	22853740
Chevrolet	Camaro	2015	315MHz	31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	
Chevrolet	Camaro	2015	433MHz	31R105						433MHz	Yes	Schrader	22853740
Chevrolet	Camaro	2016	Sub Model: ZL1	31R105	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Schrader	22959748
Chevrolet	Camaro	2016	Excluding ZL1	31R105			17-20045		11.5 (screw)	433MHz	Yes	Schrader	
Chevrolet	Camaro	2017-2018	Clamp-In Valve							433MHz	Yes	Schrader	13598772
Chevrolet	Camaro	2017-2018	Snap-In Valve	31R105			17-20045		11.5 (screw)	433MHz	Yes	Schrader	13598773
Chevrolet	Caprice	2011-2013		31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	Caprice	2014-2016		31R109		17-20223AK				315MHz	Yes	Schrader	13581559
Chevrolet	Captiva Sport	2012-2013		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20925924
Chevrolet	Captiva Sport	2014-2015		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Chevrolet	Chevyenne	2014					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Chevrolet	City Express	2015-2017								315MHz	Yes	Schrader	19316553
Chevrolet	Cobalt	2008-2009	w/ Schrader Clamp-In	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	Cobalt	2008-2009	w/ Siemens Clamp-In	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Chevrolet	Cobalt	2008-2009	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Cobalt	2010		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	12768826
Chevrolet	Colorado	2006-2012		31R108		17-20006AK		1	62(7)	315MHz	Yes	Schrader	15122618
Chevrolet	Colorado	2015-2016		31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Chevrolet	Colorado	2017-2018					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Corvette	1997-2000		31R103		17-20012AK		1	62(7)	315MHz	Yes	Schrader	10438853
Chevrolet	Corvette	2001-2004		31R103		17-20028AK		3	62(7)	315MHz	Yes	Schrader	25773946
Chevrolet	Corvette	2005-2009		31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25758220
Chevrolet	Corvette	2010-2012	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15268606
Chevrolet	Corvette	2010-2012	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	Corvette	2013		31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	Corvette	2014-2016	USA Only	31R304		17-20223AK				433MHz	Yes	Schrader	13581560
Chevrolet	Corvette	2017-2018		31R304						433MHz	Yes	Schrader	13598775
Chevrolet	Cruze	2011-2012		31R105			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20922900

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Chevrolet	Cruze	2013					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Cruze	2014-2015					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Cruze	2016-2017					17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773
Chevrolet	Cruze Limited	2016					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Equinox	2007-2009	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Chevrolet	Equinox	2007-2009	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Chevrolet	Equinox	2010-2012					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	12768826
Chevrolet	Equinox	2013-2014					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Equinox	2015					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13589597
Chevrolet	Equinox	2016-2018					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13589597
Chevrolet	Express 1500	2008-2009	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Chevrolet	Express 1500	2008-2009	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Chevrolet	Express 1500	2008-2009	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Express 1500	2010-2012					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Chevrolet	Express 1500	2013-2015					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Express 1500	2016					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Chevrolet	Express 1500	2017					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598771
Chevrolet	Express 2500-4500	2008-2009	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Chevrolet	Express 2500-4500	2008-2009	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Chevrolet	Express 2500-4500	2008-2009	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Express 2500-4500	2010-2012					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Chevrolet	Express 2500-4500	2013-2016					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Express 2500-4500	2017					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598771
Chevrolet	G Series	2008	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	10394110
Chevrolet	G Series	2008	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	10394110
Chevrolet	HHR	2008-2009	w/ Siemens Clamp-In	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15268606
Chevrolet	HHR	2008-2009	w/ Schrader Clamp-In	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	HHR	2008-2009	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	HHR	2010					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	12768826
Chevrolet	HHR	2011	Grey Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	HHR	2011	Black Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Impala	2006	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15268606
Chevrolet	Impala	2006	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	Impala	2007	w/ Siemens Clamp-In	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15268606
Chevrolet	Impala	2007	w/ Schrader Clamp-In	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	Impala	2007	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Chevrolet	Impala	2008-2012					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Impala	2013					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Impala	2014-2015					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Impala	2016-2018					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Impala Limited	2014					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13586335
Chevrolet	Impala Limited	2015-2016					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	2345327
Chevrolet	Malibu	2008	w/ Siemens Clamp-In	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Chevrolet	Malibu	2008	w/ Schrader Clamp-In	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Chevrolet	Malibu	2008	w/ Schrader Snap-In	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	15922396
Chevrolet	Malibu	2009-2012					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	15922396
Chevrolet	Malibu	2013-2015					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Malibu	2016					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Malibu	2017-2018					17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773
Chevrolet	Monte Carlo	2006	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15268606
Chevrolet	Monte Carlo	2006	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	Monte Carlo	2007	w/ Siemens Clamp-In	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15268606
Chevrolet	Monte Carlo	2007	w/ Schrader Clamp-In	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	Monte Carlo	2007	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Chevrolet	Oriando	2012-2014					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	12768826
Chevrolet	Silverado	2004				17-20107AK		4	62(7)	315MHz	Yes	Schrader	15136883
Chevrolet	Silverado	2005-2006				17-20107AK		4	62(7)	315MHz	Yes	Schrader	15114379
Chevrolet	Silverado	2007	w/ TRW Clamp-In	31R108		17-20015AK		3	62(7)	315MHz	Yes	TRW	15825475
Chevrolet	Silverado	2007	w/ Snap In	31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	15825475
Chevrolet	Silverado	2007	w/ Siemens Clamp-In	31R108		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15825475
Chevrolet	Silverado	2007	w/ Schrader Clamp-In	31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15825475
Chevrolet	Silverado	2008-2016					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Chevrolet	Silverado	2017-2018	315MHz				17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Silverado	2017-2018	433MHz				17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773
Chevrolet	Sonic	2012-2015					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Sonic	2016-2018					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Spark	2016					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Spark	2013-2016					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Spark	2017-2018					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Spark EV	2014-2016					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	SS	2014-2015						4	62(7)	315MHz	Yes	Schrader	13581559
Chevrolet	SS	2016						4	62(7)	315MHz	Yes	Schrader	13598786
Chevrolet	SSR	2006-2007	TPMS Optional	31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25774006
Chevrolet	Suburban	2004					17-20107AK	4	62(7)	315MHz	Yes	Schrader	15136883
Chevrolet	Suburban	2005-2006					17-20107AK	4	62(7)	315MHz	Yes	Schrader	15114379
Chevrolet	Suburban	2007	w/ TRW Clamp-In	31R108		17-20015AK		3	62(7)	315MHz	Yes	TRW	15825475
Chevrolet	Suburban	2007	w/ Siemens Clamp-In	31R108		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15825475
Chevrolet	Suburban	2007	w/ Schrader Clamp-In	31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15825475
Chevrolet	Suburban	2007	w/ Snap-In Sensor	31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Chevrolet	Suburban	2008-2012					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Chevrolet	Suburban	2013-2014					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Chevrolet	Suburban	2015-2016					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Chevrolet	Suburban	2017-2018					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Suburban	2017-2018					17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Chevrolet	Tahoe	2004		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15136883
Chevrolet	Tahoe	2005-2006		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15114379
Chevrolet	Tahoe	2007	w/ TRW Clamp-In	31R108		17-20015AK		3	62(7)	315MHz	Yes	TRW	15825475
Chevrolet	Tahoe	2007	w/ Siemens Clamp-In	31R108		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15825475
Chevrolet	Tahoe	2007	w/ Schrader Clamp-In	31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15825475
Chevrolet	Tahoe	2007	w/ Snap-In Sensor	31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Chevrolet	Tahoe	2008-2012		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Chevrolet	Tahoe	2018	315MHz				17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Tahoe	2013-2014		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Chevrolet	Tahoe	2018	433MHz				17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773
Chevrolet	Tahoe	2015-2017		31R118			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
Chevrolet	TrailBlazer	2006-2009		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25774006
Chevrolet	Traverse	2009-2014		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
Chevrolet	Traverse	2015					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	23445327
Chevrolet	Traverse	2016-2017		31R109			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598771
Chevrolet	Traverse	2018					17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13516165
Chevrolet	Trax	2015					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Trax	2016-2018		31R109			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
Chevrolet	Uplander	2008	With Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15268606
Chevrolet	Uplander	2008	With Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Chevrolet	Volt	2011-2015		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Volt	2016		31R109			17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	22854866
Chevrolet	Volt	2017		31R109			17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773
CHRYSLER													
Chrysler	200	2011-2014		31R302	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	68078861AA
Chrysler	200	2015-2016		31R302			17-50397		n/a	433MHz	Yes	Continental	68193586AC
Chrysler	200	2017		31R302						433MHz	Yes		68313387AB
Chrysler	300	2005-2007		31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	68111696AA
Chrysler	300	2008		31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	68001698AB
Chrysler	300	2009		31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AE
Chrysler	300	2010	w/ Snap-In Sensor	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AA
Chrysler	300	2010	w/ Clamp-In Sensor	31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AE
Chrysler	300	2011		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AA
Chrysler	300	2012-2014	Exc: SRT8	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Chrysler	300	2012-2014	SRT8	31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AE
Chrysler	300	2015-2016		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	68241067AB
Chrysler	300	2017-2018		31R302						433MHz	Yes	Schrader	68241067AB
Chrysler	300C	2014-2015	w/ Snap-In Sensor	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Chrysler	300C	2014-2015	w/ Clamp-In Sensor	31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AE
Chrysler	300M	2002-2004		31R409			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	Aspen	2007-2009	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56029465AB
Chrysler	Aspen	2007-2009	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029465AB
Chrysler	Concorde	2002-2004		31R409			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	Crossfire	2004		31R302			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	Crossfire	2005	315MHz: w/ Siemens Sensor	31R411			17-20201AK	5	80(9)	315MHz	Yes	Siemens	5142340AAA
Chrysler	Crossfire	2005	433MHz	31R411			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	Crossfire	2005	315MHz: w/ Schrader Sensor	31R411	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56053030AB
Chrysler	Crossfire	2006-2008	433MHz	31R411			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	Crossfire	2006-2008	315MHz: w/ Siemens Sensor	31R411			17-20201AK	5	80(9)	315MHz	Yes	Siemens	56053030AB
Chrysler	Crossfire	2006-2008	315MHz: w/ Schrader Sensor	31R411	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56053030AB
Chrysler	Intrepid	2002-2004		31R302			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	Pacifica	2003		31R302			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	Pacifica	2004	315MHz: AFTER VIN R499999	31R302			17-20201AK	5	80(9)	315MHz	Yes	Siemens	51273355AB
Chrysler	Pacifica	2004	433MHz: BEFORE VIN R500000	31R302			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	Pacifica	2005		31R302			17-20201AK	5	80(9)	315MHz	Yes	Siemens	51273355AB
Chrysler	Pacifica	2006-2008	w/ Siemens Sensor	31R302			17-20201AK	5	80(9)	315MHz	Yes	Siemens	68001696AB
Chrysler	Pacifica	2006-2008	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Chrysler	Pacifica	2017-2018								433MHz	Yes		68313387AB
Chrysler	Prowler	2002		31R302			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	PT Cruiser	2008-2010	w/ Siemens Sensor	31R302			17-20201AK	5	80(9)	315MHz	Yes	Siemens	68001696AB
Chrysler	PT Cruiser	2008-2010	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Chrysler	Sebring	2007	w/ Siemens Sensor	31R302			17-20201AK	5	80(9)	315MHz	Yes	Siemens	68001696AB
Chrysler	Sebring	2007	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Chrysler	Sebring	2008-2009	315MHz: w/ Siemens Sensor	31R302			17-20201AK	5	80(9)	315MHz	Yes	Siemens	68001696AB
Chrysler	Sebring	2008-2009	315MHz: w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Chrysler	Sebring	2008-2009	433MHz: w/ Siemens Sensor	31R302			17-20201AK	5	80(9)	433MHz	Yes	Siemens	68001698AB
Chrysler	Sebring	2008-2009	433MHz: w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	68001698AB
Chrysler	Sebring	2010-2011	w/ Siemens Sensor	31R302			17-20201AK	5	80(9)	315MHz	Yes	Siemens	68001696AB
Chrysler	Sebring	2010-2011	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Chrysler	Town & Country	2002-2003		31R409			17-20028AK	3	62(7)	433MHz	Yes	Schrader	52088990AC
Chrysler	Town & Country	2004-2005		31R302			17-20201AK	5	80(9)	315MHz	Yes	Siemens	51273355AB
Chrysler	Town & Country	2006-2007	w/ Siemens Sensor	31R411			17-20201AK	5	80(9)	315MHz	Yes	Siemens	56053030AB
Chrysler	Town & Country	2006-2007	w/ Schrader Sensor	31R411	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56053030AB
Chrysler	Town & Country	2008-2010	w/ Siemens Sensor	31R302			17-20201AK	5	80(9)	433MHz	Yes	Siemens	68001698AB
Chrysler	Town & Country	2008-2010	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	68001698AB
Chrysler	Town & Country	2011-2013		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AA
Chrysler	Town & Country	2014-2016		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	68241067AA
Chrysler	Voyager	2002-2003		31R409		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
DODGE													

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Dodge	Avenger	2008-2009	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	68001696AB
Dodge	Avenger	2008-2009	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Dodge	Avenger	2010-2012	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68078861AA
Dodge	Avenger	2010-2012	w/ Continental Sensor	31R302	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	68078861AA
Dodge	Avenger	2013-2014		31R302	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	68078861AA
Dodge	Caliber	2007-2010	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	68001696AB
Dodge	Caliber	2007-2010	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Dodge	Caliber	2011-2012	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68078861AA
Dodge	Caliber	2011-2012	w/ Continental Sensor	31R302	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	68078861AA
Dodge	Caravan	2002-2003		31R302		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
Dodge	Caravan	2004-2005		31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	5127335AB
Dodge	Caravan	2006-2007	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56053030AB
Dodge	Caravan	2006-2007	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56053030AB
Dodge	Challenger	2008-2009		31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AD
Dodge	Challenger	2010-2012	w/ Snap-In Sensor	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AA
Dodge	Challenger	2010-2012	w/ Clamp-In Sensor	31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AD
Dodge	Challenger	2013-2018	w/ Snap-In Sensor	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	68241067AA
Dodge	Challenger	2013-2018	w/ Clamp-In Sensor	31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AE
Dodge	Charger	2006-2007	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	68001696AB
Dodge	Charger	2006-2007	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Dodge	Charger	2008	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	68001698AB
Dodge	Charger	2008	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	68001698AB
Dodge	Charger	2009		31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AC
Dodge	Charger	2010-2018	w/ Snap-In Sensor	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AA
Dodge	Charger	2010-2018	w/ Clamp-In Sensor	31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AC
Dodge	Dakota	2008-2010		31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029319AC
Dodge	Dakota	2011		31R302			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	56029479AA
Dodge	Dart	2013-2016		31R201			17-50397		n/a	433MHz	Yes	Continental	68193586AC
Dodge	Durango	2007-2010	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56029465AB
Dodge	Durango	2007-2010	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029465AB
Dodge	Durango	2011-2015		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Dodge	Durango	2016		31R302			17-50397		n/a	433MHz	Yes	Continental	68252493AA
Dodge	Durango	2017-2018		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	68313387AB
Dodge	Durango SRT	2018		31R302						433MHz	Yes	Continental	68252495AA
Dodge	Grand Caravan	2002-2003		31R302		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
Dodge	Grand Caravan	2004-2005		31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	5127335AB
Dodge	Grand Caravan	2006-2007	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56053030AB
Dodge	Grand Caravan	2006-2007	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56053030AB
Dodge	Grand Caravan	2008-2010	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	68001698AB
Dodge	Grand Caravan	2008-2010	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	68001698AB
Dodge	Grand Caravan	2011-2017		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Dodge	Intrepid	2002-2004		31R302		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
Dodge	Journey	2009	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	68001698AB
Dodge	Journey	2009	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	68001698AB
Dodge	Journey	2010	hi-line	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AA
Dodge	Journey	2010	w/ Siemens Sensor; lo-line	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	68001698AB
Dodge	Journey	2010	w/ Schrader Sensor; lo-line	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	68001698AB
Dodge	Journey	2011-2017		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Dodge	Magnum	2005-2007	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	68001696AB
Dodge	Magnum	2005-2007	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Dodge	Magnum	2008	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	68001698AB
Dodge	Magnum	2008	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	68001698AB
Dodge	Magnum	2009		31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AD
Dodge	Nitro	2007-2009	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56029479AA
Dodge	Nitro	2010-2012	w/ Schrader Clamp-In	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029479AA
Dodge	Ram	2008	w/ Clamp-In Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029319AC
Dodge	Ram	2008	w/ Snap-In Sensor	31R302			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	68137699AA
Dodge	Ram	2009	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	56029359AC
Dodge	Ram	2009	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	56029359AC
Dodge	Ram	2010	w/ Clamp-In Sensor; Lo-Line	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	56029359AC
Dodge	Ram	2010	w/ Snap-In Sensor; Hi-Line	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Dodge	Sprinter	2007-2013		31R302	17-20198AK			4	53(6)	315MHz	Yes	Siemens	68038945AA
Dodge	Stratus	2007	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56053030AB
Dodge	Stratus	2007	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56053030AB
Dodge	Viper	2003-2010		31R411		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
Dodge	Viper	2012-2016		31R411		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AE
FERRARI													
Ferrari	599	2004-2011				17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	224549
Ferrari	458 Italia	2010-2015				17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	-
Ferrari	550 Maranello	2010-2012				17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	224549

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Ferrari	557 M Maranello	2002-2006			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)			Beru	-
Ferrari	612 Scaglietti	2004-2011			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	224549
Ferrari	California	2000-2014			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	228887
Ferrari	Enzo	2003			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	224551
Ferrari	Enzo	2004			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	-
Ferrari	F12 Berlinetta	2013-2015								433MHz	Yes		-
Ferrari	F430	2006-2011			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)			Beru	-
Ferrari	FF	2012-2015								433MHz	Yes		-
Ferrari	Spider	2002-2009			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	224549
FIAT													
Fiat	500	2011-2016		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Fiat	500L	2014-2018		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Fiat	500X	2016		31R302			17-50397		n/a	433MHz	Yes	Continental	68193586AC
FORD													
Ford	C-Max	2013-2017		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	C-Max	2018		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	DE8T-1A180-AA
Ford	Crown Victoria	2007-2011		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Ford	E Series	2007-2009		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	8C2Z-1A189
Ford	E Series	2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	8C2Z-1A189
Ford	E Series	2010		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	E Series	2011-2016		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Edge	2007	With 18" Chrome Wheels	31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Ford	Edge	2007	With 20" Chrome Wheels or NO Chrome	31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	7L1Z-1A-189A
Ford	Edge	2008-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	7L1Z-1A-189A
Ford	Edge	2011-2014		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Edge	2015-2017					17-20045			315MHz	Yes	Schrader	F2GZ-1A-189A
Ford	Escape	2005-2008		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Ford	Escape	2009-2018		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Expedition	2003-2004		31R102		17-20096AK		1	44(5)	433MHz	Yes	Schrader	4L2Z-1A-150BA
Ford	Expedition	2005-2006		31R102		17-20096AK		1	44(5)	315MHz	Yes	Schrader	5L1Z-1A150-AB
Ford	Expedition	2007-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	7L1Z-1A-189A
Ford	Expedition	2011-2017		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Explorer	2002-2003	Excluding Sport	31R102		17-20096AK		1	44(5)	433MHz	Yes	Schrader	4L2Z-1A-150BA
Ford	Explorer	2004-2005		31R102		17-20096AK		1	44(5)	433MHz	Yes	Schrader	4L2Z-1A-150BA
Ford	Explorer	2006-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Ford	Explorer	2011-2015		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Explorer	2016-2017					17-20045			315MHz	Yes	Schrader	F2GZ-1A189-A
Ford	F-150	2007-2008		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Ford	F-150	2009-2014		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	F-150	2015-2018					17-20045			315MHz	Yes	Schrader	F2GZ-1A189-A
Ford	F-150 HD	2008-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	8C2Z-1A189
Ford	F-250 F-350	2008-2009		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	8C2Z-1A189

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Ford	F-250 F-350	2010	Band Sensor; Before 6-29-09	31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	8C2Z-1A189
Ford	F-250 F-350	2010	Snap-In Sensor; After 6-29-09	31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	F-250 F-350	2011-2016		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	F-250 F-350	2017	6 Wheel										FR3Z-1A189-A
Ford	F-250 F-350	2017-2018	4 Wheel	31R101			17-20046						HC3Z-1A-189A
Ford	Fiesta	2011-2017		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Five Hundred	2006-2007		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	7L1Z-1A-189A
Ford	Flex	2009-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	7L1Z-1A-189A
Ford	Flex	2011-2018		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Focus	2007-2009		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	7L1Z-1A-189A
Ford	Focus	2010-2016		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Focus	2017	RS Clamp In Valve	31R102						315MHz	Yes	Schrader	G1EZ-1A-189A
Ford	Focus	2017	RS Snap In Valve	31R103			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	G1EZ-1A-189A
Ford	Focus	2017-2018	Non RS model	31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Freestar	2004-2005	TPMS Optional	31R102		17-20096AK		1	44(5)	315MHz	Yes	Schrader	5L1Z-1A150-AB
Ford	Freestar	2006-2007		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Ford	Fusion	2007-2009		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Ford	Fusion	2010-2017		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Fusion	2018		31R101			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	HC3Z-1A-189B
Ford	Mustang	2007-2009		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Ford	Mustang	2010-2012		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Mustang	2013-2014	Excluding Shelby GT500	31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Mustang	2013-2014	Shelby GT500	31R101			17-50390		11.5 (screw)	315MHz	Yes		DR3Z-1A189A
Ford	Mustang	2015-2017		31R115			17-20018			315MHz	Yes	Schrader	F2GZ-1A189-A
Ford	Police Interceptor	2013-2015		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Ranger	2007-2012		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Ford	Special Service Police Sedan	2015					17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Taurus	2008-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Ford	7L1Z-1A-189A
Ford	Taurus	2011-2018		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Ford	Transit (All)	2010-2018		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
FREIGHTLINER													
Freightliner	Sprinter	2007-2013			17-20198AK			4	53(6)	315MHz	Yes	Siemens	68038945AA
Freightliner	Sprinter	2014-2016				17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 72 00
GENESIS													
Genesis	G80	2017		31R205	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	52933-3N100
GMC													
GMC	Acadia	2007-2008	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
GMC	Acadia	2007-2008	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
GMC	Acadia	2009-2016		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
GMC	Acadia	2017	Old Body Style				17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598771
GMC	Acadia	2017-2018	New Body Style				17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13598773
GMC	Canyon	2007-2012		31R108		17-20006AK		1	62(7)	315MHz	Yes	Schrader	15122618
GMC	Canyon	2015-2017					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
GMC	Canyon	2018					17-20045	2	11.5 (screw)	315MHz	Yes	Schrader	13598772
GMC	Envoy	2005-2006		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	25774006
GMC	Envoy	2007-2009	Clamp-In	31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15825475
GMC	Envoy	2007-2009	Snap-In Sensor	31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
GMC	Savana	2008-2009	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
GMC	Savana	2008-2009	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
GMC	Savana	2010-2016		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
GMC	Savana	2017		31R109			17-20045	2		315MHz	Yes	Schrader	13586335
GMC	Sierra	2004		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15136883
GMC	Sierra	2007	Clamp-In	31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15825475
GMC	Sierra	2007	Snap-In Sensor	31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
GMC	Sierra	2005-2006		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15114379
GMC	Sierra	2008-2014		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
GMC	Sierra	2015-2016	single rear wheel	31R118			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13581558
GMC	Sierra	2018					17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13516164
GMC	Terrain	2010-2014					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	20923680
GMC	Terrain	2015-2017					17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	13589597
GMC	Terrain	2018					17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13516164
GMC	Yukon	2004		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15136883
GMC	Yukon	2005-2006		31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15114379
GMC	Yukon	2007	Clamp-In	31R108		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15825475
GMC	Yukon	2007	Snap-In Sensor	31R108			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
GMC	Yukon	2008-2015		31R118			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
GMC	Yukon	2016-2017					17-20008	2		315MHz	Yes	Schrader	13581558
GMC	Yukon	2018					17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	13516164
HONDA													
Honda	Accord	2008-2012		31R204			17-20216AK	1	35(4)	315MHz	Yes	Pacific	42753-SWA-316
Honda	Accord	2013-2018	Indirect TPMS										
Honda	Accord Crosstour	2010-2011		31R204	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	42753-TP6-A82
Honda	Civic	2008-2011		31R204			17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-SNA-A83
Honda	Civic	2012-2014		31R204			17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-TRO-A81
Honda	Civic	2015	Indirect TPMS										
Honda	Crosstour	2010-2015		31R204	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	42753-TP6-A82
Honda	CR-V	2007-2011		31R204			17-20216AK	1	35(4)	315MHz	Yes	Pacific	42753-SWA-315
Honda	CR-V	2012-2013		31R204	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	42753-TP6-A82
Honda	CR-V	2014-2015	Indirect TPMS										
Honda	CR-Z	2011-2015		31R204			17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-TR3-A81
Honda	Element	2006-2008		31R204	17-20036AK	17-20206AK		4/2	35(4)	315MHz		TRW	06421-SCV-A00
Honda	Element	2009-2011		31R204			17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-TR3-A81
Honda	Fit	2008		31R204			17-20216AK	1	35(4)	315MHz	Yes	Pacific	42753-SWA-316
Honda	Fit	2009-2014		31R204			17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-TR3-A81
Honda	Fit	2015-2018	Indirect TPMS										
Honda	HR-V Crossover	2016-2018	Indirect TPMS										
Honda	Insight	2010-2014		31R204			17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-SNA-A83
Honda	Odyssey	2005		31R204	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	06421-S3V-A04
Honda	Odyssey	2006-2010	Touring	31R305	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	06421-S3V-A04
Honda	Odyssey	2006-2010	Non Touring	31R204	17-20036AK	17-20206AK		4/2	35(4)	315MHz		TRW	06421-SCV-A00
Honda	Odyssey	2011-2016		31R204			17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-TR3-A81
Honda	Odyssey	2017-2018								433MHz	Yes	Continental	42753-TG7-A51
Honda	Pilot	2005	w/ Steel Wheels	31R305	17-20035AK	17-20206AK		4/1	35(4)	315MHz		TRW	06421-S3V-A02
Honda	Pilot	2005	w/ Alloy Wheels	31R305	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	06421-S3V-A04
Honda	Pilot	2006-2008		31R305	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	06421-S3V-A04
Honda	Pilot	2009		31R204			17-20216AK	1	35(4)	315MHz		Pacific	42753-STK-A04
Honda	Pilot	2010-2015	LX	31R204			17-20216AK	1	35(4)	315MHz		Pacific	42753-SZA-A13
Honda	Pilot	2010-2015	Exc. LX	31R204			17-20216AK	1	35(4)	315MHz		Pacific	42753-STK-A04
Honda	Pilot	2016-2018								433MHz	Yes	Continental	42753-TG7-A51
Honda	Ridgeline	2006-2008	Exc. RT	31R305	17-20036AK	17-20206AK		4/2	35(4)	315MHz		TRW	06421-S3V-A04
Honda	Ridgeline	2006-2008	RT	31R305	17-20035AK	17-20206AK		4/1	35(4)	315MHz		TRW	06421-S9V-A03
Honda	Ridgeline	2009		31R305	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	06421-S3V-A04
Honda	Ridgeline	2010-2014	Exc. RT	31R305			17-20204AK	3	35(4)	315MHz	Yes	TRW	42753-SHJ-A53
Honda	Ridgeline	2010-2014	RT	31R305	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	06421-S3V-A04
Honda	Ridgeline	2017-2018								433MHz	Yes	Continental	42753-T6N-A01
Honda	S2000	2008-2009		31R204			17-20216AK	1	35(4)	315MHz	Yes	Pacific	42753-S2A-315
HUMMER													
Hummer	H2	2008-2010		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Hummer	H3	2006-2010		31R108			17-20006AK	1	62(7)	315MHz	Yes	Schrader	15122618
Hummer	H3T	2009-2010		31R108			17-20006AK	1	62(7)	315MHz	Yes	Schrader	15122618
HYUNDAI													
Hyundai	Accent	2006-2007		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	52933-1F000
Hyundai	Accent	2008-2011		31R205			17-20204AK	3	35(4)	315MHz	Yes	TRW	52933-2F000
Hyundai	Accent	2012-2013		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M000
Hyundai	Accent	2014	Before 10-15-13	31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M000
Hyundai	Accent	2014	After 10-15-13	31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M550
Hyundai	Accent	2015-2017		31R205			17-20720AK	5	71(8)	433MHz	Yes	Continental	52933-3N100
Hyundai	Azera	2007-2011		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-2G200
Hyundai	Azera	2012-2017		31R205			17-20204AK	3	35(4)	315MHz		TRW	52933-3V000
Hyundai	Elantra	2007-2008		31R205	17-20036AK	17-20206AK	17-50391	4/2	35(4)	315MHz	Yes	Lear	52933-2G200
Hyundai	Elantra	2009-2010	Non Touring	31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-2G200
Hyundai	Elantra	2009-2010	Touring: With Continental Sensor	31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2L500
Hyundai	Elantra	2009-2010	Touring: With Siemens Sensor	31R205			17-20201AK	5	80(9)	315MHz	Yes	Siemens	52933-2L500
Hyundai	Elantra	2011-2012	Non Touring	31R205			17-20204AK	3	35(4)	315MHz		TRW	52933-3X200
Hyundai	Elantra	2011-2012	Touring: With Continental Sensor	31R205	17-20725AK	17-20720AK	17-50391	5	71(8)	315MHz	Yes	Continental	52933-2L500
Hyundai	Elantra	2011-2012	Touring: With Siemens Sensor	31R205			17-20201AK	5	80(9)	315MHz	Yes	Siemens	52933-2L500
Hyundai	Elantra	2013		31R205			17-20204AK	3	35(4)	315MHz		TRW	52933-3X200
Hyundai	Elantra	2014-2016		31R205			17-50391	3	35(4)	315MHz	Yes	TRW	52933-3X205
Hyundai	Elantra	2017-2018		31R205						433MHz	Yes	Continental	52933-F2000
Hyundai	Elantra Coupe	2013-2014		31R205			17-20204AK	3	35(4)	315MHz	Yes	TRW	52933-3X200
Hyundai	Elantra GT	2013		31R205	17-20725AK	17-20720AK	17-50391	5	71(8)	315MHz	Yes	Continental	52933-A5000
Hyundai	Elantra GT	2014-2018		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-3N000
Hyundai	Entourage	2007-2010		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-4D200
Hyundai	Equus	2011-2013		31R205			17-20204AK	3	35(4)	315MHz	Yes	TRW	52933-2F000
Hyundai	Equus	2014-2016		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-3N000
Hyundai	Genesis	2009-2014		31R205			17-20204AK	3	35(4)	315MHz	Yes	TRW	52933-2F000
Hyundai	Genesis	2015-2017		31R205	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	52933-3N100
Hyundai	Genesis Coupe	2010-2012		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M000
Hyundai	Genesis Coupe	2013-2015		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M550
Hyundai	Ioniq	2017								433MHz	Yes	Continental	52933-F2000
Hyundai	Santa Fe	2007		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-4D200
Hyundai	Santa Fe	2008	lo-line	31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-4D200
Hyundai	Santa Fe	2008	hi-line	31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-4D200

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Hyundai	Santa Fe	2009		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-2G200
Hyundai	Santa Fe	2010-2012		31R205			17-50399		11.5 (nut)	315MHz		Lear	52933-0W100
Hyundai	Santa Fe	2013-2014		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-A5000
Hyundai	Santa Fe	2015-2017		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-3N000
Hyundai	Santa Fe Sport	2013-2014		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-A5000
Hyundai	Santa Fe Sport	2015-2017		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-3N000
Hyundai	Sonata	2007		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	52933-3E000
Hyundai	Sonata	2008	FM	31R205		17-20204AK		3	35(4)	315MHz	Yes	TRW	52933-2F000
Hyundai	Sonata	2008	AM	31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	52933-3E000
Hyundai	Sonata	2009-2010		31R205		17-20204AK		3	35(4)	315MHz	Yes	TRW	52933-2F000
Hyundai	Sonata	2011-2014		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M000
Hyundai	Sonata	2014		31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M550
Hyundai	Sonata	2015-2017	Hybrid	31R205	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-A5000
Hyundai	Sonata	2015-2018	Exc: Hybrid	31R205			17-20046		11.5 (nut)	433MHz	Yes	Schrader	52933-C1100
Hyundai	Tiburon	2007-2008		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	52933-1F000
Hyundai	Tucson	2007-2009		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	52933-1F000
Hyundai	Tucson	2010	FM	31R205		17-20204AK		3	35(4)	315MHz	Yes	TRW	52933-2F000
Hyundai	Tucson	2010	AM	31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	52933-3E000
Hyundai	Tucson	2011-2014		31R205		17-20204AK		3	35(4)	315MHz	Yes	TRW	52933-2F000
Hyundai	Tucson	2015		31R205			17-20046		11.5 (screw)	315MHz	Yes		52933-2S500
Hyundai	Tucson	2016-2017		31R205			17-20046		11.5 (nut)	433MHz	Yes	Schrader	52933-C1100
Hyundai	Veloster	2012-2017		31R205			17-20008		11.5 (screw)	315MHz	Yes	Schrader	52933-2V000
Hyundai	Veracruz	2007		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-4D200
Hyundai	Veracruz	2008	LO-LINE	31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-4D200
Hyundai	Veracruz	2008	HI-LINE	31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-4D200
Hyundai	Veracruz	2009-2012		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-2G200
INFINITI													
Infiniti	EX35	2008-2009		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00C
Infiniti	EX35	2010	Before May	31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00C
Infiniti	EX35	2010	After April	31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	EX35	2011-2014		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	EX37	2013		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	FX35	2003-2006		31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	FX35	2007	Before July	31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	FX35	2007	After June	31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Infiniti	FX35	2008		31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Infiniti	FX35	2009		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00C
Infiniti	FX35	2010	Before May	31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00C
Infiniti	FX35	2010	After April	31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	FX35	2011-2014		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	FX37	2013		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	FX45	2003-2006		31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	FX45	2007	Before July	31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	FX45	2007	After July	31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Infiniti	FX45	2008		31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Infiniti	FX50	2009		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00C
Infiniti	FX50	2010	Before May	31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00C
Infiniti	FX50	2010	After April	31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	FX50	2011-2014		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	G25	2011-2014		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	G35	2003-2006		31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	G35	2007	With Schrader Sensor	31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Infiniti	G35	2007	With Pacific Sensor	31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK01B
Infiniti	G35	2008		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK01B
Infiniti	G37	2008-2009		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00C
Infiniti	G37	2010	Before May	31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00C
Infiniti	G37	2010	After April	31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	G37	2011-2014		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	JX35	2013		31R206	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3JA0A
Infiniti	M35	2006-2007		31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	M35	2008-2010		31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1A00C
Infiniti	M35h	2012-2013		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0E
Infiniti	M37	2011-2014		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	M45	2003-2007		31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	M45	2008-2010		31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1A00C
Infiniti	M56	2011-2014		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Infiniti	Q30	2016		31R206						433MHz	Yes		A000 905 0030 Q05
Infiniti	Q40	2015		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0E
Infiniti	Q45	2003-2005		31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	Q45	2006	Before July	31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	Q45	2006	After August	31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA02B
Infiniti	Q50	2014-2015		31R206	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-4GA0A
Infiniti	Q50	2016-2017		31R209	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3JA0B
Infiniti	Q60	2014-2016		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0D
Infiniti	Q60	2017		31R206	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3JA0B
Infiniti	Q70	2014-2018		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0E
Infiniti	QX30	2016-2017								433MHz	Yes		A000 905 0030 Q05
Infiniti	QX4	2003		31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Infiniti	QX50	2014-2017		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0E

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Infiniti	QX56	2004-2006	w/ Alloy Wheels	31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Infiniti	QX56	2004-2006	w/ Steel Wheels	31R206		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Infiniti	QX56	2007	Before April	31R206		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Infiniti	QX56	2007	After March	31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA02B
Infiniti	QX56	2008-2010		31R206		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA02B
Infiniti	QX56	2011-2014		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LAOC
Infiniti	QX60	2014-2018		31R206	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3JA0B
Infiniti	QX70	2014-2017		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LAOE
Infiniti	QX80	2014-2016		31R206		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LAOE
Infiniti	QX80	2017		31R206						433MHz	Yes	Pacific	40700-6WYOB
ISUZU													
Isuzu	Ascender	2006-2008		31R110		17-20107AK		4	62(7)	315MHz	Yes	Schrader	8257740060
Isuzu	I290	2007-2008		31R110		17-20006AK		1	62(7)	315MHz	Yes	Schrader	8151226180
Isuzu	I370	2007-2008		31R110		17-20006AK		1	62(7)	315MHz	Yes	Schrader	8151226180
Isuzu	Rodeo	2004		31R207		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
JAGUAR													
Jaguar	F-Pace	2016								433MHz	Yes	Continental	C2D43636
Jaguar	F-Type	2014-2016								433MHz		Continental	C2D43636
Jaguar	S-Type	2007-2008	433MHz	31R428		17-20201AK		5	80(9)	433MHz		Siemens	C2215016
Jaguar	S-Type	2007-2008	315MHz	31R428		17-20201AK		5	80(9)	315MHz		Siemens	C2215017
Jaguar	Vanden Plas	2004-2009	315MHz	31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2C25519
Jaguar	Vanden Plas	2004-2009	433MHz	31R428		17-20201AK		5	80(9)	433MHz	Yes	Siemens	C2540710
Jaguar	XE	2016								433MHz	Yes	Continental	C2D43636
Jaguar	XF	2009	315MHz	31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2C40476
Jaguar	XF	2016								433MHz	Yes	Continental	C2D43636
Jaguar	XF	2009	433MHz	31R428		17-20201AK		5	80(9)	433MHz	Yes	Siemens	C2540710
Jaguar	XF	2010-2015	315MHz: w/ Siemens Sensor	31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2C40476
Jaguar	XF	2010-2012	433MHz: w/ Continental Sensor	31R428	17-20725AK	17-20201AK		5	80(9)	433MHz	Yes	Siemens	C2540710
Jaguar	XF	2010-2012	433MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	C2215016
Jaguar	XF	2010-2015	315MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	C2215017
Jaguar	XFR	2012-2015	315MHz: w/ Siemens Sensor	31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2C40476
Jaguar	XFR	2012-2013	433MHz: w/ Siemens Sensor	31R428		17-20201AK		5	80(9)	433MHz	Yes	Siemens	C2540710
Jaguar	XFR	2012-2013	433MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	C2215016
Jaguar	XFR	2012-2015	315MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	C2215017
Jaguar	XJ	2004-2009	433MHz	31R428		17-20201AK		5	80(9)	433MHz	Yes	Siemens	C2215016
Jaguar	XJ	2004-2009	315MHz	31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2215017
Jaguar	XJ	2010	433MHz: w/ Siemens Sensor	31R428		17-20201AK		5	80(9)	433MHz	Yes	Siemens	C2215016
Jaguar	XJ	2010	433MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	C2215016
Jaguar	XJ	2010	315MHz: w/ Siemens Sensor	31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2215017
Jaguar	XJ	2010	315MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	C2215017
Jaguar	XJ	2011-2016	433MHz	31R428	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	C2215016
Jaguar	XJ	2011-2015	315MHz	31R428	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	C2215017
Jaguar	XK	2005-2006		31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2215017
Jaguar	XK	2007-2009	433MHz	31R428		17-20201AK		5	80(9)	433MHz	Yes	Siemens	C2215016
Jaguar	XK	2007-2009	315MHz	31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2215017
Jaguar	XK	2010-2012	433MHz: w/ Siemens Sensor	31R428		17-20201AK		5	80(9)	433MHz	Yes	Siemens	C2215016
Jaguar	XK	2010-2012	433MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	C2215016
Jaguar	XK	2010-2015	315MHz: w/ Siemens Sensor	31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2215017
Jaguar	XK	2010-2015	315MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	C2215017
Jaguar	XKR	2005-2013	433MHz: w/ Siemens Sensor	31R428		17-20201AK		5	80(9)	433MHz	Yes	Siemens	C2215016
Jaguar	XKR	2005-2013	433MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	C2215016
Jaguar	XKR	2005-2015	315MHz: w/ Siemens Sensor	31R428		17-20201AK		5	80(9)	315MHz	Yes	Siemens	C2215017
Jaguar	XKR	2005-2015	315MHz: w/ Continental Sensor	31R428	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	C2215017
JEEP													
Jeep	Cherokee	2014-2017		31R302			17-50395		11.5 (screw)	433MHz	Yes	TRW	68239720AC
Jeep	Cherokee	2018					17-50395		11.5 (screw)	433MHz	Yes	TRW	68249197AA
Jeep	Commander	2006-2007	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029465AB
Jeep	Commander	2006-2007	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	68001696AA
Jeep	Commander	2008-2010	w/ Siemens Clamp-In	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	56029359AB
Jeep	Commander	2008-2010	w/ Schrader Clamp-In	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	56029359AB
Jeep	Compass	2007-2010	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	68001696AB
Jeep	Compass	2007-2010	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Jeep	Compass	2011-2012	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Jeep	Compass	2011-2012	w/ Continental Sensor	31R302	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	68078861AA
Jeep	Compass	2013-2016		31R302			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	56029479AB
Jeep	Compass	2017-2018		31R302			17-20018			433MHz	Yes	Continental	68313387AB
Jeep	Grand Cherokee	2002-2004		31R410		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
Jeep	Grand Cherokee	2005-2007	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	68001696AB
Jeep	Grand Cherokee	2005-2007	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AB
Jeep	Grand Cherokee	2008-2010	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	56029398AB
Jeep	Grand Cherokee	2008-2010	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	56029398AB
Jeep	Grand Cherokee	2011-2013		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AA
Jeep	Grand Cherokee	2014	Snap-In	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Jeep	Grand Cherokee	2015	Snap-In	31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	68241067AA
Jeep	Grand Cherokee	2016-2018		31R302			17-20018			433MHz	Yes	Continental	68313387AB
Jeep	Grand Cherokee SRT8	2012-2015		31R302		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	56029400AE
Jeep	Grand Cherokee SRT8	2016-2018								433MHz	Yes	Continental	68252495AA
Jeep	Liberty	2004		31R410		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
Jeep	Liberty	2005-2008	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56029465AB

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Jeep	Liberty	2005-2008	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029465AB
Jeep	Liberty	2009	433MHz: w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	56029359AB
Jeep	Liberty	2009	433MHz: w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	56029359AB
Jeep	Liberty	2009	315MHz: w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56029465AB
Jeep	Liberty	2009	315MHz: w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029465AB
Jeep	Liberty	2010-2011	w/ Siemens Clamp-In	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56029465AB
Jeep	Liberty	2010-2011	w/ Schrader Clamp-In	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029465AB
Jeep	Liberty	2010-2011	w/ Schrader Snap-In	31R302			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	56029479AA
Jeep	Liberty	2012		31R302			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	56029479AA
Jeep	Patriot	2007-2010	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	68001696AA
Jeep	Patriot	2007-2010	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68001696AA
Jeep	Patriot	2011-2012	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	68078861AA
Jeep	Patriot	2011-2012	w/ Continental Sensor	31R302	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	68078861AA
Jeep	Patriot	2013-2017		31R302			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	56029479AB
Jeep	Renegade	2015-2016		31R302			17-50397	n/a		433MHz	Yes	Continental	68193586AC
Jeep	Wrangler	2007-2008	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	315MHz	Yes	Siemens	56053036AA
Jeep	Wrangler	2007-2008	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56053036AA
Jeep	Wrangler	2009	w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	56029359AB
Jeep	Wrangler	2009	w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	56029359AB
Jeep	Wrangler	2010	433MHz: w/ Siemens Sensor	31R302		17-20201AK		5	80(9)	433MHz	Yes	Siemens	56029359AB
Jeep	Wrangler	2010	433MHz: w/ Schrader Sensor	31R302	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	433MHz	Yes	Schrader	56029359AB
Jeep	Wrangler	2007-2012	w/ Snap-In Sensor: 315MHz	31R302			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	56029479AA
Jeep	Wrangler	2011-2012		31R302			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	56029479AA
Jeep	Wrangler	2013-2018		31R302			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
KIA													
Kia	Amanti	2007-2011		31R306	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	52933-3E000
Kia	Borrego	2009-2011		31R306		17-20204AK		3	35(4)	315MHz	Yes	TRW	52933-2F000
Kia	Cadenza	2014	18" Wheels: Before August		17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-A5000
Kia	Cadenza	2014-2016	19" Wheels: After August	31R306	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M550
Kia	Cadenza	2017								433MHz	Yes	Continental	52933-D9100
Kia	Forte	2010-2013		31R306	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M000
Kia	Forte	2014-2015		31R306		17-20204AK	17-50391	3	35(4)	315MHz	Yes	Continental	52933-A7000
Kia	Forte	2016-2017		31R306						315MHz	Yes		52933-3X205
Kia	K900	2015-2016		31R306						433MHz		Schrader	52933-3T000
Kia	Magentis	2008-2010		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-2G200
Kia	Mohave	2009		31R306		17-20204AK		3	35(4)	315MHz	Yes	TRW	52933-2F000
Kia	Niro	2017								433MHz	Yes	Continental	52933-D4100
Kia	Optima	2006-2010		31R205	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-2G200
Kia	Optima	2011-2013		31R306	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M000
Kia	Optima	2014-2015		31R306	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M550
Kia	Optima	2016-2018								433MHz	Yes		52933-D4100
Kia	Optima Hybrid	2016		31R306	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M550
Kia	Optima Hybrid	2017		31R306	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M550
Kia	Rio	2007-2011		31R306		17-20204AK		3	35(4)	315MHz	Yes	TRW	52933-2F000
Kia	Rio	2012-2017		31R306		17-20204AK	17-50391	3	35(4)	433MHz		TRW	52933-3X200
Kia	Rio	2018		31R306						433MHz	Yes		
Kia	Rondo	2007-2010		31R306	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-2G200
Kia	Rondo	2014			17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	Lear	52933-4D700
Kia	Sedona	2006-2008		31R306	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-4D200
Kia	Sedona	2009-2013		31R306	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-2G200
Kia	Sedona	2014		31R306	17-20036AK	17-20206AK		4/2	35(4)	315MHz		Lear	52933-4D700
Kia	Sedona	2015-2017					17-20046	2	11.5 (nut)	433MHz	Yes	Schrader	52933-B2100
Kia	Sorento	2005-2010		31R306	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	52933-3E000
Kia	Sorento	2011-2013		31R306	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M000
Kia	Sorento	2014-2015		31R306	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M000
Kia	Sorento	2016-2018						5	71(8)	433MHz	Yes	Continental	52933-3N100
Kia	Soul	2010-2013		31R306	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	52933-2M000
Kia	Soul	2014-2017		31R306			17-20046	2	11.5 (nut)	433MHz	Yes	Schrader	52933-B2100
Kia	Spectra	2006-2009		31R306		17-20204AK		3	35(4)	315MHz	Yes	TRW	52933-2F000
Kia	Sportage	2006-2007		31R306	17-20036AK	17-20206AK		4/2	35(4)	315MHz	Yes	TRW	52933-3E000
Kia	Sportage	2008-2013		31R306		17-20204AK		3	35(4)	315MHz	Yes	TRW	52933-2F000
Kia	Sportage	2014-2016		31R306		17-20204AK	17-50391	3	35(4)	315MHz	Yes		52933-2S500
Kia	Sportage	2017-2018								433MHz	Yes	Continental	52933-D9100
LAMBORGHINI													
Lamborghini	Aventador	2012-2016			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	7PP-907-275F
Lamborghini	Gallardo	2007-2013			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4FO-907-275B
Lamborghini	Huracan	2015			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	7PP-907-275F
Lamborghini	Murcielago	2007-2011			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4FO-907-275B

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Lamborghini	Reventon	2008			17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	7PP-907-275F
LAND ROVER													
Land Rover	LR2	2013		31R430		17-20201AK		5	80(9)	315MHz		Siemens	LR018859
Land Rover	LR2	2008-2009		31R430		17-20201AK		5	80(9)	315MHz		Siemens	LR018859
Land Rover	LR2	2010-2012	315MHz; Siemens Sensor	31R430		17-20201AK		5	80(9)	315MHz		Siemens	LR018859
Land Rover	LR2	2010-2012	315MHz; Continental Sensor	31R430	17-20725AK	17-20720AK		5	71(8)	315MHz		Continental	LR032833
Land Rover	LR2	2010-2012	433MHz; Continental Sensor	31R430	17-20725AK	17-20720AK		5	71(8)			Continental	LR018861
Land Rover	LR2	2010-2012	433MHz; Siemens Sensor	31R430		17-20201AK		5	80(9)			Siemens	LR018861
Land Rover	LR3	2002-2005		31R430	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)			Beru	YBD000060
Land Rover	LR3	2006-2009	433MHz	31R430		17-20201AK		5	80(9)			Siemens	LR010532
Land Rover	LR3	2006-2009	315MHz	31R430		17-20201AK		5	80(9)	315MHz	Yes	Siemens	LR010533
Land Rover	LR4	2012-2013	Siemens Sensor	31R430		17-20201AK		5	80(9)			Siemens	LR032833
Land Rover	LR4	2012-2013	Continental Sensor	31R430	17-20725AK	17-20720AK		5	71(8)	315MHz		Continental	LR032833
Land Rover	LR4	2010-2011	315MHz; Continental Sensor	31R430	17-20725AK	17-20720AK		5	71(8)	315MHz		Continental	LR032833
Land Rover	LR4	2010-2011	433MHz; Continental Sensor	31R430	17-20725AK	17-20720AK		5	71(8)			Continental	LR018861
Land Rover	LR4	2010-2011	315MHz; Siemens Sensor	31R430		17-20201AK		5	80(9)	315MHz		Siemens	LR018859
Land Rover	LR4	2010-2011	433MHz; Siemens Sensor	31R430		17-20201AK		5	80(9)			Siemens	LR018861
Land Rover	Range Rover	2006-2009	433MHz	31R430		17-20201AK		5	80(9)			Continental	LR010532
Land Rover	Range Rover	2006-2009	315MHz	31R430		17-20201AK		5	80(9)	315MHz	Yes	Siemens	LR010533
Land Rover	Range Rover	2010	433MHz	31R430		17-20201AK		5	80(9)			Continental	LR010532
Land Rover	Range Rover	2010	315MHz; w/ Siemens Sensor	31R430		17-20201AK		5	80(9)	315MHz		Siemens	LR010533
Land Rover	Range Rover	2010	315MHz; w/ Continental Sensor	31R430	17-20725AK	17-20720AK		5	71(8)	315MHz		Continental	LR021936
Land Rover	Range Rover	2011-2013		31R430	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	LR021936
Land Rover	Range Rover	2014-2016								433MHz	Yes	Continental	LR066378
Land Rover	Range Rover Evoque	2012-2013		31R430	17-20725AK	17-20720AK		5	71(8)	315MHz		Continental	LR010533
Land Rover	Range Rover Evoque	2014-2016								433MHz	Yes	Continental	LR066378
Land Rover	Range Rover Sport	2006-2009		31R430	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	LR018860
Land Rover	Range Rover Sport	2010-2013		31R430	17-20725AK	17-20720AK		5	71(8)	315MHz		Continental	LR010533
Land Rover	Range Rover Sport	2014-2016								433MHz	Yes	Continental	LR066378
LEXUS													
Lexus	CT 200h	2011-2017		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	ES Series	2013-2015		31R212		17-20216AK		1	35(4)	315MHz		Pacific	42607-30060
Lexus	ES Series	2016-2017				17-20216AK		1	35(4)	315MHz		Pacific	42607-06020
Lexus	ES Series	2018		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-30060
Lexus	ES350	2007-2012		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	GS300	2005-2006	OEM Sensor 42607-30030	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-30030
Lexus	GS300	2005-2006	OEM Sensor 42607-33021	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	GS350	2007-2012		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	GS350	2013-2017		31R212		17-20216AK		1	35(4)	315MHz		Pacific	42607-30060
Lexus	GS430	2005		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-30030
Lexus	GS430	2006	Before July	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-30030
Lexus	GS430	2006	After June	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	GS430	2007		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	GS450h	2007-2012		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	GS450h	2013-2017		31R212		17-20216AK		1	35(4)	315MHz		Pacific	42607-30060
Lexus	GS460	2008-2011		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	GX460	2010-2017		31R208		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	GX470	2004-2005		31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-35010
Lexus	GX470	2006	After January	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	GX470	2006	Jan 31 and Older	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-35010
Lexus	GX470	2007-2009		31R208		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	HS250h	2010-2012		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-75010
Lexus	IS F	2008-2013		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	IS F	2014-2015		31R212		17-20216AK		1	35(4)	315MHz		Pacific	42607-30060
Lexus	IS250 IS350	2006	Before April	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-30030
Lexus	IS250 IS350	2006	After March	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	IS250 IS350	2007-2013		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	IS250 IS350	2014-2017		31R212		17-20216AK		1	35(4)	315MHz		Pacific	42607-30060
Lexus	LC 500	2018		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-48010
Lexus	LFA	2012-2015		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	LS460	2007-2012		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	LS460	2013-2016		31R212		17-20216AK		1	35(4)	315MHz		Pacific	42607-30060
Lexus	LS600h	2008-2012		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	LS600h	2013-2017		31R212		17-20216AK		1	35(4)	315MHz		Pacific	42607-30060
Lexus	LX470	2005		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-24010
Lexus	LX470	2006	Before August	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-24010
Lexus	LX470	2006	After July	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	LX470	2007-2009		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	LX570	2008-2017		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	NX200t	2015-2018		31R212		17-20216AK		1	35(4)	315MHz		Pacific	42607-30060
Lexus	NX300h	2015-2018		31R212		17-20216AK		1	35(4)	315MHz		Pacific	42607-30060
Lexus	RC F	2015-2016		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-30060
Lexus	RC350	2015-2017		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-30060
Lexus	RX Series	2016		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-48010

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Lexus	RX Series	2016		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-48010
Lexus	RX330	2006		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	RX350	2007-2015	Japan Built	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	RX350	2007-2015	Non Japan Built	31R212		17-20216AK							42607-0E011
Lexus	RX400h	2007-2008	18" Wheels	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-0E011
Lexus	RX400h	2007-2008	17" Wheels	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	RX400h	2009-2015		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	RX450h	2010-2015		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Lexus	SC430	2002-2006		31R212		17-20221AK		3	27(3)			Pacific	42607-24010/20/30/40
Lexus	SC430	2007-2010		31R208		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
LINCOLN													
Lincoln	Continental	2017	433Mhz	31R101			17-20018			433MHz	Yes		F2GZ-1A189-B
Lincoln	Continental	2017-2018	315Mhz	31R101			17-20018			315MHz	Yes	Schrader	F2GZ-1A189-A
Lincoln	MKC	2015-2016		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Lincoln	MKC	2017-2018	315Mhz	31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Lincoln	MKC	2017-2018	433Mhz	31R101			17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	BB5Z-1A-189A
Lincoln	MKZ	2017-2018	315Mhz	31R101			17-20018			315MHz	Yes	Schrader	F2GZ-1A189-A
Lincoln	MKZ	2017-2018	433Mhz	31R101			17-20018			433MHz	Yes		F2GZ-1A189-B
Lincoln	Aviator	2003-2005		31R102		17-20096AK		1	44(5)	433MHz	Yes	Schrader	4L2Z-1A-150BA
Lincoln	Mark LT	2007-2008		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Lincoln	MKS	2009-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	7L1Z-1A-189A
Lincoln	MKS	2016					17-20018			315MHz	Yes	Schrader	F2GZ-1A189-A
Lincoln	MKS	2011-2015		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Lincoln	MKS	2016-2017		31R101			17-20018			315MHz	Yes	Schrader	F2GZ-1A189-A
Lincoln	MKT	2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	7L1Z-1A-189A
Lincoln	MKT	2011-2015		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Lincoln	MKT	2016-2018					17-20018			315MHz	Yes	Schrader	F2GZ-1A189-A
Lincoln	MKX	2007	With 18" Chrome Wheels	31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Lincoln	MKX	2007	With 20" Chrome Wheels or NO Chrome	31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	7L1Z-1A-189A
Lincoln	MKX	2008-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	7L1Z-1A-189A
Lincoln	MKX	2011-2015		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Lincoln	MKX	2016-2018					17-20018			315MHz	Yes	Schrader	F2GZ-1A189-A
Lincoln	MKZ	2007-2008		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Lincoln	MKZ	2009	Before 02-04-09	31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Lincoln	MKZ	2009	After 02-04-09	31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Lincoln	MKZ	2010-2016		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Lincoln	MKZ	2017-2018		31R101			17-20046	2	11.5 (screw)	315MHz	Yes	Schrader	
Lincoln	Navigator	2003-2004		31R102		17-20096AK		1	44(5)	433MHz	Yes	Schrader	4L2Z-1A-150BA
Lincoln	Navigator	2005-2006		31R102		17-20096AK		1	44(5)	315MHz	Yes	Schrader	5L1Z-1A150-AB
Lincoln	Navigator	2007-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	7L1Z-1A-189A
Lincoln	Navigator	2011-2017		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Lincoln	Town Car	2006-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Lincoln	Town Car	2011	Band Sensor	31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Lincoln	Town Car	2011	Snap-In	31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Lincoln	Town Car	2012		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
MAZDA													
Mazda	2	2011-2013	w/ Siemens Sensor	31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	BBM2-37-140B
Mazda	2	2011-2013	w/ Continental Sensor	31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BBM2-37-140B
Mazda	2	2014		31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BHA4-37-140
Mazda	3	2004		31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	FE01-37-140A
Mazda	3	2005-2010		31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	GN3A-37-140B
Mazda	3	2011-2013	w/ Siemens Sensor	31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	BBM2-37-140B
Mazda	3	2011-2013	w/ Continental Sensor	31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BBM2-37-140B
Mazda	3	2014-2018	Indirect TPMS										-
Mazda	5	2006-2010		31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	GN3A-37-140B
Mazda	5	2011-2012	w/ Siemens Sensor	31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	BBM2-37-140B
Mazda	5	2011-2012	w/ Continental Sensor	31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BBM2-37-140B
Mazda	5	2013-2015		31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BHA4-37-140
Mazda	6	2005-2010		31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	GN3A-37-140B
Mazda	6	2011-2013	w/ Siemens Sensor	31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	BBM2-37-140B
Mazda	6	2011-2013	w/ Continental Sensor	31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BBM2-37-140B
Mazda	6	2014-2016	Indirect TPMS										-

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Mazda	B Series	2007-2009		31R111		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	ZZC1-37-140
Mazda	CX-5	2012-2016	Indirect TPMS										
Mazda	CX-5	2017-2018		31R307	17-20720AK			5	71(8)	315MHz	Yes	Continental	BHA4-37-140
Mazda	CX-6	2014-2015	Indirect TPMS										
Mazda	CX-7	2007-2009		31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	GN3A-37-140B
Mazda	CX-7	2010-2012	w/ Continental Sensor	31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BBM2-37-140B
Mazda	CX-7	2010-2012	w/ Siemens Sensor	31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	GN3A-37-140B
Mazda	CX-9	2007-2009		31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	BBM2-37-140B
Mazda	CX-9	2010-2013	w/ Continental Sensor	31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BBM2-37-140B
Mazda	CX-9	2010-2013	w/ Siemens Sensor	31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	GN3A-37-140B
Mazda	CX-9	2017-2018		31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BHA4-37-140
Mazda	CX-9	2014-2015		31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BHA4-37-140
Mazda	MX-5 Miata	2006-2009		31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	BBM2-37-140B
Mazda	MX-5 Miata	2010-2013	w/ Continental Sensor	31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BBM2-37-140B
Mazda	MX-5 Miata	2010-2013	w/ Siemens Sensor	31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	GN3A-37-140B
Mazda	MX-5 Miata	2014-2015		31R307	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	BHA4-37-140
Mazda	RX-8	2004		31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	FE01-37-140A
Mazda	RX-8	2005-2011		31R307		17-20201AK		5	80(9)	315MHz	Yes	Siemens	GN3A-37-140B
Mazda	Tribute	2006-2008		31R111		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Mazda	Tribute	2009	Band Sensor	31R111		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Mazda	Tribute	2009	Snap-In	31R111			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	ZZDA-37-140
Mazda	Tribute	2010-2011		31R111			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	ZZDA-37-140
MERCEDES													
Mercedes	A Class	2016-2017		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	AMG GT	2018		31R434		17-20216AK						Schrader	000 905 00 30
Mercedes	B Class	2014-2017		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	C Class	2007-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	C Class	2014	Before Dec23 2013			17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 72 00
Mercedes	C Class	2014-2018	After Dec 23 2013	31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	CL Class	2000-2009	433MHz	31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	000 822 3306
Mercedes	CL Class	2000-2009	315MHz	31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	000 822 3406
Mercedes	CL Class	2010	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	CL Class	2010	433MHz	31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	CL Class	2011-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	CLA Class	2014-2018		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	CLK Class	2006		31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	000 822 3406
Mercedes	CLK Class	2007	315MHz	31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	000 822 3406
Mercedes	CLK Class	2007	433MHz	31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	003 540 0217
Mercedes	CLK Class	2008-2009		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	003 540 0217
Mercedes	CLS Class	2006-2011	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	CLS Class	2006-2011	433MHz	31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	CLS Class	2012-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	CLS Class	2014-2018		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	E Class	2000-2005	315MHz	31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	000 822 3406
Mercedes	E Class	2000-2005	433MHz	31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	000 822 3306
Mercedes	E Class	2006-2009	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	E Class	2006-2009	433MHz	31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	E Class	2010-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	E Class	2014-2016		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	E Class	2017-2018		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 2102
Mercedes	E Class Coupe	2017		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	G Class	2007-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	003 540 0217
Mercedes	G Class	2014-2017		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	GL Class	2007-2009	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	GL Class	2007-2009	433MHz	31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	GL Class	2010-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	GL Class	2014-2017		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	GLA Class	2015-2018		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 72 00
Mercedes	GLC	2016-2018		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	GLE Class	2016-2018		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Mercedes	GLK Class	2010-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	GLK Class	2014-2016		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	GLS	2017-2018		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	GT-S	2016		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	Metris	2016-2017		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	ML Class	2006-2008	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	ML Class	2006-2008	433MHz	31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	ML Class	2009		31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	ML Class	2010-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	ML Class	2015-2016		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	R Class	2006-2008	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	R Class	2006-2008	433MHz	31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	R Class	2009		31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	R Class	2010-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	S Class	2000-2006	315MHz	31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	000 822 3406
Mercedes	S Class	2000-2006	433MHz	31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	000 822 3306
Mercedes	S Class	2007-2009	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	S Class	2007-2009	433MHz	31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	S Class	2010-2011	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	S Class	2010-2011	433MHz	31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	S Class	2012-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	S Class	2014-2018		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	SL Class	2006-2011	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	SL Class	2006-2011	433MHz	31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	SL Class	2012		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	SL Class	2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 72 00
Mercedes	SL Class	2014-2018		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	SLK Class	2008-2012		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	SLK Class	2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 72 00
Mercedes	SLK Class	2014-2016		31R434		17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
Mercedes	SLR Class	2000-2003		31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	000 822 3306
Mercedes	SLR Class	2004-2006	315MHz	31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	000 822 3406
Mercedes	SLR Class	2004-2006	433MHz	31R434	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	000 822 3306
Mercedes	SLR Class	2008-2009	315MHz	31R434		17-20203AK		3	53(6)	315MHz	Yes	Siemens	002 540 7917
Mercedes	SLR Class	2008-2009	433MHz	31R434		17-20203AK		3	53(6)	433MHz	Yes	Siemens	002 540 8017
Mercedes	SLS	2011-2013		31R434		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
Mercedes	Sprinter	2014-2017				17-20216AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 00 30
MERCURY													
Mercury	Grand Marquis	2006-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Mercury	Grand Marquis	2011	Band Sensor	31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Mercury	Grand Marquis	2011	Snap-In	31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Mercury	Mariner	2006-2008		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Mercury	Mariner	2009-2011		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Mercury	Milan	2007-2009		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Mercury	Milan	2010-2011		31R101			17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A
Mercury	Montego	2006-2007		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	7L1Z-1A-189A
Mercury	Monterey	2004-2005		31R102		17-20096AK		1	44(5)	315MHz	Yes	Schrader	5L1Z-1A150-AB
Mercury	Monterey	2006-2007		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Mercury	Mountaineer	2002-2005		31R102		17-20096AK		1	44(5)	433MHz	Yes	Schrader	4L2Z-1A-150BA
Mercury	Mountaineer	2006-2010		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	6F2Z-1A-189A
Mercury	Sable	2008-2009		31R101		17-21101, 17-21102, 17-21103				315MHz	Yes	Lear	7L1Z-1A-189A
MINI													

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Mini	Cabrio	2014-2015		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	HUF	36 10 6 798 872
Mini	Cabrio	2016-2017		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Continental	36 10 6 881 890
Mini	Cabrio	2004-2006	Indirect TPMS										Indirect TPMS
Mini	Clubman	2014-2017		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Continental	36 10 6 856 209
Mini	Cooper	2007-2009		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	BERU	36 23 6 781 847
Mini	Cooper	01/2010-02/2014		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	HUF	36 10 6 856 227
Mini	Cooper	03/2014-12/2017		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Continental	36 10 6 856 209
Mini	Countryman	2015-2017		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	HUF	36 10 6 798 872
Mini	Hardtop	2004-2006	Indirect TPMS										Indirect TPMS
Mini	Hatchback	2014-2017		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Continental	36 10 6 856 209
Mini	Paceman	2015-2016		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	HUF	36 10 6 798 872
Mini	Roadster	03/2014-12/2015		31R435	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	HUF	36 10 6 798 872
MITSUBISHI													
Mitsubishi	Eclipse	2006-2007	w/ steel wheels	31R437		17-20010AK		2	80(9)	315MHz	Yes	Schrader	4250A030
Mitsubishi	Eclipse	2006-2007	w/ Alloy Wheels	31R437		17-20028AK		3	62(7)	315MHz	Yes	Schrader	MN103081
Mitsubishi	Eclipse	2008-2010		31R437		17-20028AK		3	62(7)	315MHz	Yes	Schrader	MN103081
Mitsubishi	Eclipse	2011-2012		31R437		17-20028AK		3	62(7)	315MHz	Yes	Schrader	4250B877
Mitsubishi	Endeavor	2004-2005		31R437		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
Mitsubishi	Endeavor	2006	After August	31R437		17-20028AK		3	62(7)	315MHz	Yes	Schrader	4250B877
Mitsubishi	Endeavor	2006	Before September	31R437		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
Mitsubishi	Endeavor	2007-2011		31R437		17-20028AK		3	62(7)	315MHz	Yes	Schrader	MN103081
Mitsubishi	Galant	2004-2006		31R437		17-20028AK		3	62(7)	433MHz	Yes	Schrader	MN103033
Mitsubishi	Galant	2007-2012	w/ Steel Wheels	31R437		17-20010AK		2	80(9)	315MHz	Yes	Schrader	4250A030
Mitsubishi	Galant	2007-2012	w/ Alloy Wheels	31R437		17-20028AK		3	62(7)	315MHz	Yes	Schrader	4250B877
Mitsubishi	i-MiEV	2010-2017		31R437	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	4250B975
Mitsubishi	Lancer	2008		31R437		17-20201AK		5	80(9)	315MHz	Yes	Siemens	4250A225
Mitsubishi	Lancer	2009	Before August	31R437		17-20201AK		5	80(9)	315MHz	Yes	Siemens	4250A225
Mitsubishi	Lancer	2009	After August	31R437	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	4250B668
Mitsubishi	Lancer	2010-2017		31R437	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	4250B975
Mitsubishi	Mirage	2014-2016			17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	4250B975
Mitsubishi	Mirage	2017-2018			17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	4250D585
Mitsubishi	Montero	2003-2006		31R437		17-20028AK		3	62(7)	315MHz	Yes	Schrader	MN103081
Mitsubishi	Outlander	2007-2008		31R437		17-20201AK		5	80(9)	315MHz	Yes	Siemens	4250A225
Mitsubishi	Outlander	2009	w/ Siemens Sensor	31R437		17-20201AK		5	80(9)	315MHz	Yes	Siemens	4250A225
Mitsubishi	Outlander	2009	w/ Continental Sensor	31R437	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	4250B975
Mitsubishi	Outlander	2010-2018		31R437	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	4250B975
Mitsubishi	Raider	2008-2010		31R437	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	56029319AB
Mitsubishi	RVR	2010-2015		31R437	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	4250B975
Mitsubishi	RVR	2018		31R437	17-20720AK			5	71(8)	315MHz	Yes	Continental	4250B975
NISSAN													
Nissan	350Z	2003-2006		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Nissan	350Z	2007-2009		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0C
Nissan	370Z	2008-2010		31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00C
Nissan	370Z	2011-2014		31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Nissan	370Z	2015-2018		31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Nissan	Altima	2006-2012		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Nissan	Altima	2015-2017		31R209	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3JA0B
Nissan	Altima Coupe	2013-2014		31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3A00A
Nissan	Altima Sedan	2013-2014		31R209	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3JA0B
Nissan	Armada	2005-2006	w/ Alloy Wheels	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Armada	2005-2006	w/ Steel Wheels	31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Armada	2007		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Armada	2008	SE	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Armada	2008	LE	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Nissan	Armada	2009-2016		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Nissan	Armada	2017		31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN0A
Nissan	Cube	2009-2010		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0D
Nissan	Cube	2011	w/o Intelligent Key	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0D
Nissan	Cube	2011	w/ Intelligent Key	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN1A
Nissan	Cube	2012	Base	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Cube	2012	S With Man Trans < March	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Cube	2012	S With Man Trans > March	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00E
Nissan	Cube	2012-2014	S CVT Trans	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0D
Nissan	Cube	2013-2014	SL	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN1A
Nissan	Cube	2013-2014	S Man Trans	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00E
Nissan	Frontier	2003-2004		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Nissan	Frontier	2005-2006	w/ Alloy Wheels	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Frontier	2005-2006	w/ Steel Wheels	31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Frontier	2007-2011		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Nissan	Frontier	2012-2015	w/ Continental Sensor	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN0A
Nissan	Frontier	2012-2015	w/ Schrader Sensor	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0D
Nissan	Frontier	2016-2017		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0D
Nissan	Frontier	2018		31R209	17-20720AK			5	71(8)	315MHz	Yes	Continental	40700-3AN0A
Nissan	GT-R	2009-2016		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Juke	2011	S	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Juke	2011	SL	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Nissan	Juke	2011	SV	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Nissan	Juke	2012	S: To 03/2012	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Juke	2012	S: From 03/2012	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK01A
Nissan	Juke	2012	SL: From 02/2012	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0D
Nissan	Juke	2012	SL: To 02/2012	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN1A
Nissan	Juke	2012	SV: From 02/2012	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0D
Nissan	Juke	2012	SV: To 02/2012	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN1A
Nissan	Juke	2013-2015	S: without I-Key	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK01A
Nissan	Juke	2013-2015	Exc. S: with I-Key	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0E
Nissan	Juke	2016-2017		31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0E
Nissan	Leaf	2010-2013		31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Nissan	Leaf	2014-2017		31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN1B
Nissan	Maxima	2006		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Maxima	2007	After April	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Maxima	2007	Before April	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Maxima	2008-2011		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Maxima	2012	w/ Schrader; Before Dec	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Maxima	2012	w/ Continental; After Dec	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN0A
Nissan	Maxima	2013-2015		31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN0A
Nissan	Maxima	2016-2017		31R209	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3JA0B
Nissan	Murano	2003-2006		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Nissan	Murano	2007-2012		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Murano	2013-2014		31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK01A
Nissan	Murano	2015-2018		31R209	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3JA0B
Nissan	NV1500 2500 3500	2012-2016		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1PA0A
Nissan	NV200	2013-2017		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0D
Nissan	Pathfinder	2003		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Nissan	Pathfinder	2004	Before August	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CD001
Nissan	Pathfinder	2004	After August	31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Pathfinder	2005	w/ Alloy Wheels	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Pathfinder	2005	w/ Steel Wheels	31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Pathfinder	2006		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Pathfinder	2007	Before December	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Pathfinder	2007	After December	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Nissan	Pathfinder	2008-2012		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0D
Nissan	Pathfinder	2013-2018		31R209	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3JA0A
Nissan	Quest	2004		31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Quest	2005-2006	w/ Alloy Wheels	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Quest	2005-2006	w/ Steel Wheels	31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Quest	2007-2010		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-JA01B
Nissan	Quest	2011-2017		31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-1LA0C
Nissan	Rogue	2008-2012		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Rogue	2013		31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00E
Nissan	Rogue	2014-2016		31R209	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	40700-3VU0A
Nissan	Rogue Select	2014		31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK01B
Nissan	Sentra	2007	w/ Alloy Wheels	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Sentra	2007	w/ Steel Wheels	31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Sentra	2008-2012		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Sentra	2013-2016	w/o Intelligent Key	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN0A
Nissan	Sentra	2013-2017	w/ Intelligent Key	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN1B
Nissan	Titan	2004		31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Titan	2005	w/ Alloy Wheels	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Titan	2005	w/ Steel Wheels	31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Titan	2006		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Titan	2007	w/ Alloy Wheels; Before April	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Titan	2007	w/ Steel Wheels; After April	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Titan	2008-2013		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0B
Nissan	Titan	2014	Chrome Wheels	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AA0D

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Nissan	Titan	2014	Exc. Chrome Wheels	31R209						315MHz	Yes	Continental	40700-3ANOC
Nissan	Titan	2015		31R209						315MHz	Yes	Continental	40700-3ANOC
Nissan	Versa	2007-2011		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AAOB
Nissan	Versa	2012	1.6	31R209	17-20725AK			5	71(8)	315MHz	Yes	Continental	40700-3ANOA
Nissan	Versa	2012	1.8 Before January	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AAOD
Nissan	Versa	2012	1.8 After January	31R209		17-20216AK		1	35(4)	315MHz	Yes	Pacific	40700-JK00D
Nissan	Versa	2013-2014	S and SV	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3ANOA
Nissan	Versa	2013-2014	SL	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3AN1A
Nissan	Versa	2015		31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3ANOB
Nissan	Versa Note	2014-2015		31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3ANOA
Nissan	Xterra	2003-2004		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Xterra	2005		31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Xterra	2006	w/ Alloy Wheels	31R209		17-20007AK		2	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK001
Nissan	Xterra	2006	w/ Steel Wheels	31R209		17-20005AK		1	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-CK002
Nissan	Xterra	2007-2011		31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AAOB
Nissan	Xterra	2012-2015	Continental	31R209	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	40700-3ANOA
Nissan	Xterra	2012-2015	Schrader	31R209		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	40700-1AADD
PLYMOUTH													
Plymouth	Prowler	1997-2001		31R411		17-20012AK		1	62(7)	433MHz	Yes	Schrader	04815132AB
Plymouth	Prowler	2002		31R411		17-20028AK		3	62(7)	433MHz	Yes	Schrader	52088990AC
PONTIAC													
Pontiac	G3	2009-2010		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Pontiac	G5	2008	w/ Siemens Clamp-In	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Pontiac	G5	2008	w/ Schrader Clamp-In	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Pontiac	G5	2008	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Pontiac	G5	2009-2010		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Pontiac	G6	2008	w/ Siemens Clamp-In	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Pontiac	G6	2008	w/ Schrader Clamp-In	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Pontiac	G6	2008	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Pontiac	G6	2009-2010		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Pontiac	G8	2008-2009		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
Pontiac	Grand Prix	2007-2008	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Pontiac	Grand Prix	2007-2008	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Pontiac	Montana	2008-2009	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15268606
Pontiac	Montana	2008-2009	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15268606
Pontiac	Solstice	2008-2010	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	15921013
Pontiac	Solstice	2008-2010	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	15921013
Pontiac	Torrent	2006-2009	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)	315MHz	Yes	Siemens	10394110
Pontiac	Torrent	2006-2009	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)	315MHz	Yes	Schrader	10394110
Pontiac	Vibe	2008-2010		31R202		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Pontiac	Wave	2008-2009		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
PORSCHE													
Porsche	911	2005	433MHz	31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	99760602101
Porsche	911	2006-2008	315MHz	31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	315MHz	Yes	Beru	997 606 021 01
Porsche	911	2006-2008	433MHz	31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	99760602101
Porsche	911	2009-2015		31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	99760602120
Porsche	Boxster	2006-2008	315MHz	31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	315MHz	Yes	Beru	997 606 021 01
Porsche	Boxster	2006-2008	433MHz	31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	99760602100
Porsche	Boxster	2009-2016		31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	99760602120
Porsche	Carrera GT	2003-2006		31R438		17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	0532207001
Porsche	Cayenne	2002		31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	95536166100
Porsche	Cayenne	2003-2006	433MHz	31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)	433MHz	Yes	Beru	95536166100
Porsche	Cayenne	2003-2006	315MHz	31R438		17-50340, 17-50342, 17-50344, 17-50346		4	35(4)			Beru	95536166111

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION			
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN		
Porsche	Cayenne	2007-2008		31R438	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	95560602100		
Porsche	Cayenne	2009	315MHz	31R438	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	95560602300		
Porsche	Cayenne	2009	433MHz	31R438	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	95560602100		
Porsche	Cayenne	2010	315MHz	31R438	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	95560602300		
Porsche	Cayenne	2010	433MHz	31R438	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	95836166100		
Porsche	Cayenne	2011-2014		31R308	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	95836166100		
Porsche	Cayenne	2015-2016								433MHz	Yes	HUF	5Q0-907-275		
Porsche	Cayman	2006-2008	433MHz	31R308	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	99760602100		
Porsche	Cayman	2006-2012	315MHz	31R438	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	7PP-907-275G		
Porsche	Cayman	2009-2016	433MHz	31R308	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	99760602120		
Porsche	Macan	2015-2016								433MHz	Yes	HUF	5Q0-907-275		
Porsche	Panamera	2010-2011	315MHz	31R438	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	99760602321		
Porsche	Panamera	2010-2011	433MHz	31R438	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	99760602100		
Porsche	Panamera	2012-2013		31R438	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	99760602100		
Porsche	Panamera	2014-2016								433MHz	Yes	HUF	5Q0-907-275		
RAM															
Ram	C/V	2013-2015		31R302					17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Ram	Cargo	2015		31R302					17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AB
Ram	Pro Master	2014-2017		31R302								433MHz	Yes	Schrader	5154876AA
Ram	Ram 1500 - 4500	2011-2013		31R302					17-20018	2	11.5 (screw)	433MHz	Yes	Schrader	56029398AA
Ram	Ram 1500 2500	2014-2017		31R302					17-50395		11.5 (screw)	433MHz	Yes	TRW	68157568AB
Ram	Ram 1500 2500	2018		31R302					17-50395		11.5 (screw)	433MHz	Yes	TRW	68249197AA
Ram	Ram 3500	2014-2017	Dual Rear Wheels (Steel Inside Wheels)	31R302					17-50395		11.5 (screw)	433MHz	Yes	TRW	68239725AC
Ram	Ram 3500	2014-2017	Dual Rear Wheels (Aluminum Outside Wheels)	31R302					17-50396			433MHz	Yes	TRW	68239729AB
Ram	Ram 3500	2014-2018	Dual Rear Wheels (Steel Outside Wheels)	31R302					17-50395		11.5 (screw)	433MHz	Yes	TRW	68249197AA
SAAB															
Saab	9-3	2004-2007		31R309		17-20010AK		2	80(9)			433MHz		Schrader	13172567
Saab	9-3	2008-2012		31R309		17-20010AK		2	80(9)		Yes	433MHz		Schrader	12768826
Saab	9-5	2004-2007		31R309		17-20010AK		2	80(9)			433MHz		Schrader	13172567
Saab	9-5	2008-2012		31R309		17-20010AK		2	80(9)		Yes	433MHz		Schrader	13227143
Saab	9-5	2010-2012		31R105			17-20008	2	11.5 (screw)		Yes	315MHz	Yes	Schrader	13581558
Saab	9-4X	2012		31R309			17-20008	2	11.5 (screw)		Yes	315MHz	Yes	Schrader	20922900
Saab	9-7X	2005-2009		31R112		17-20107AK		4	62(7)		Yes	315MHz	Yes	Schrader	25774006
SATURN															
Saturn	Astra	2008-2009		31R109		17-20010AK		2	80(9)			433MHz		Schrader	13172567
Saturn	Astra	2010	Grey Sensor	31R109			17-20008	2	11.5 (screw)		Yes	315MHz	Yes	Schrader	12768826
Saturn	Astra	2010	Black Sensor	31R109			17-20008	2	11.5 (screw)		Yes	315MHz	Yes	Schrader	12768826
Saturn	Aura	2007	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)		Yes	315MHz	Yes	Siemens	15921013
Saturn	Aura	2007	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)		Yes	315MHz	Yes	Schrader	15921013
Saturn	Aura	2008-2010		31R109			17-20008	2	11.5 (screw)		Yes	315MHz	Yes	Schrader	25920615
Saturn	Lambda Crossover	2007-2008	w/ Siemens Sensor	31R109		17-20202AK		2	71(8)		Yes	315MHz	Yes	Siemens	15921013
Saturn	Lambda Crossover	2007-2008	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)		Yes	315MHz	Yes	Siemens	15921013
Saturn	Outlook	2007	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)		Yes	315MHz	Yes	Siemens	15921013
Saturn	Outlook	2007	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)		Yes	315MHz	Yes	Schrader	15921013
Saturn	Outlook	2008	w/ Siemens Clamp-In	31R109		17-20201AK		5	80(9)		Yes	315MHz	Yes	Siemens	15921013
Saturn	Outlook	2008	w/ Schrader Clamp-In	31R109		17-20107AK		4	62(7)		Yes	315MHz	Yes	Schrader	15921013
Saturn	Outlook	2008	w/ Snap-In Sensor	31R109			17-20008	2	11.5 (screw)		Yes	315MHz	Yes	Schrader	25920615
Saturn	Outlook	2009-2010		31R109			17-20008	2	11.5 (screw)		Yes	315MHz	Yes	Schrader	25920615
Saturn	Sky	2007-2009	w/ Siemens Sensor	31R109		17-20201AK		5	80(9)		Yes	315MHz	Yes	Siemens	15921013
Saturn	Sky	2007-2009	w/ Schrader Sensor	31R109		17-20107AK		4	62(7)		Yes	315MHz	Yes	Schrader	15921013

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Saturn	Vue	2007-2010		31R109			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	25920615
SCION													
Scion	FR-S	2013-2016		31R212		17-20216AK		1	35(4)	315MHz		Pacific	SU003-00754
Scion	IA	2015-2016	Indirect TPMS										
Scion	IM	2016				17-20216AK		1	35(4)	315MHz		Pacific	42607-06020
Scion	iQ	2011-2015		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Scion	tC	2006-2016		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Scion	xB	2007-2015		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Scion	xD	2008-2015		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
SMART													
Smart	Fortwo	2008	w/ Schrader Sensor	31R439		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	35400217
Smart	Fortwo	2008	w/ Siemens Sensor	31R439		17-20203AK		3	53(6)	433MHz	Yes	Siemens	45421518
Smart	Fortwo	2009-2012		31R439		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	35400217
Smart	Fortwo	2013-2015		31R439		17-20016AK	17-20020	1	53(6)	433MHz	Yes	Schrader	000 905 4100
SUBARU													
Subaru	B9 Tribeca	2006-2008		31R210		17-20011AK		3	66(7.5)	315MHz	Yes	Schrader	28103AG00A
Subaru	BRZ	2013-2018		31R210		17-20216AK		1	35(4)	315MHz		Pacific	28103-CA000
Subaru	Forester	2008-2013		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103AG01C
Subaru	Forester	2014-2018		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103SG000
Subaru	Impreza	2008-2013		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103AG01C
Subaru	Impreza	2014-2016		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103SA002
Subaru	Impreza	2017-2018		31R210			17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	28103-FL00A
Subaru	Legacy	2004-2007		31R210		17-20011AK		3	66(7.5)	315MHz	Yes	Schrader	28103AG00A
Subaru	Legacy	2008	Clamp-In	31R210		17-20011AK		3	66(7.5)	315MHz	Yes	Schrader	28103AG00A
Subaru	Legacy	2008	Snap-In	31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103AG01C
Subaru	Legacy	2009-2017		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103AG01C
Subaru	Legacy	2018		31R210			17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	28103-FL00A
Subaru	Outback	2004-2007		31R210		17-20011AK		3	66(7.5)	315MHz	Yes	Schrader	28103AG00A
Subaru	Outback	2008-2013		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103AG01C
Subaru	Outback	2014-2017		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103AJ00A
Subaru	Outback	2018		31R210			17-20045	2	11.5 (screw)	433MHz	Yes	Schrader	28103-FL00A
Subaru	Tribeca	2008-2013		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103AG01C
Subaru	Tribeca	2014		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103AJ00A
Subaru	WRX	2014-2016		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103SG000
Subaru	XV	2014		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103SG000
Subaru	XV Crosstrek	2013		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103AG01C
Subaru	XV Crosstrek	2014-2017		31R210			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	28103SG000
SUZUKI													
Suzuki	Equator	2009-2013		31R211		17-20014AK		3	49(5.5) - 66(7.5)	315MHz	Yes	Schrader	4321182Z10
Suzuki	Forenza	2007-2008		31R211			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	4313085Z03
Suzuki	Grand Vitara	2007-2013		31R113		17-20009AK		1	80(9)	315MHz	Yes	Schrader	4313054J21
Suzuki	Kizashi	2010-2013	w/ Schrader Sensor	31R211	17-20020AK	17-20013AK	17-20020	6/2	58(6.5)	315MHz	Yes	Schrader	4313057L00
Suzuki	Kizashi	2010-2013	w/ Continental Sensor	31R211	17-20725AK	17-20720AK		5	71(8)	315MHz	Yes	Continental	4313057L00
Suzuki	Reno	2007-2008		31R211			17-20008	2	11.5 (screw)	315MHz	Yes	Schrader	4313085Z00
Suzuki	SX4	2007-2012		31R113		17-20009AK		1	80(9)	315MHz	Yes	Schrader	4313054J21
Suzuki	Verona	2005-2006		31R211		17-20009AK		1	80(9)	315MHz	Yes	Schrader	4313086Z20
Suzuki	XL-7	2005-2006		31R113		17-20009AK		1	80(9)	315MHz	Yes	Schrader	4313054J21
Suzuki	XL-7	2007-2009	w/ Siemens Sensor	31R114		17-20201AK		5	80(9)	315MHz	Yes	Siemens	4313078J10
Suzuki	XL-7	2007-2009	w/ Schrader Sensor	31R114		17-20107AK		4	62(7)	315MHz	Yes	Schrader	4313078J10
TESLA													
Tesla	Model S	2013								433MHz		Baolong	6004985
Tesla	Model S	2014	Before October							433MHz		Baolong	6004985
Tesla	Model S	2014	After September			17-20725AK	17-20720AK	5	71(8)	433MHz	Yes	VDO	1034602
Tesla	Model S	2015-2016				17-20725AK	17-20720AK	5	71(8)	433MHz	Yes	VDO	1034602
Tesla	Model X	2016-2017				17-20725AK	17-20720AK	5	71(8)	433MHz	Yes	VDO	1034602
Tesla	Roadster	2008-2010	VIN 001-500							433MHz		Beru	95836166100
Tesla	Roadster	2010-2012								433MHz		Baolong	FS1511130317
TOYOTA													
Toyota	86	2017								315MHz	Yes	Pacific	SU003-06090
Toyota	4 Runner	2003-2005		31R213		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-35010
Toyota	4 Runner	2006	With OE Part 42607-33011	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	4 Runner	2006	With OE Part 42607-30030	31R213		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-30030
Toyota	4 Runner	2006	With OE Part 42607-35010	31R213		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-35010
Toyota	4 Runner	2006	With OE Part 42607-33021	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Toyota	4 Runner	2007-2009	With OE Part 42607-33011	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	4 Runner	2007-2009	With OE Part 42607-33021	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Toyota	4 Runner	2010-2018		31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Toyota	Avalon	2007-2012		31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Avalon	2013-2018		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
Toyota	Camry	2007-2011	USA Made Models	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Camry	2007-2011	Japan Made Models	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Camry	2012-2014		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
Toyota	Camry	2015-2016	Exc. Optional Instrument Cluster			17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
Toyota	Camry	2015-2018	Optional Instrument Cluster			17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06030
Toyota	Corolla	2007-2008	USA Made Models	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Corolla	2007-2008	Japan Made Models	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Corolla	2009-2011	USA Made Models (VIN STARTS WITH 1)	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Corolla	2009-2011	USA Made Models	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-02010
Toyota	Corolla	2009-2011	Japan Made Models (All Other VIN)	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011

VEHICLE INFORMATION				SERVICE KIT INFORMATION				SENSOR REPLACEMENT			OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Toyota	Corolla	2009-2011	Japan Made Models (VIN STARTS WITH J)	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Toyota	Corolla	2012-2013	USA Made Models	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Corolla	2012-2013	Japan Made Models	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Corolla	2014-2018		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
Toyota	FJ Cruiser	2008-2014		31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Highlander	2007-2009		31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Highlander	2010-2013	Japan Built	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Highlander	2010-2013	Non Japan Built	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Highlander	2014	OEM PN 06020: NON Japan Built	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
Toyota	Highlander	2014	OEM PN 0R010	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-0R010
Toyota	Highlander	2014	OEM PN 33011: Japan Built	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Highlander	2015-2017	Hybrid Limited: Limited: XLE	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
Toyota	Highlander	2015-2017	LE: LE Plus	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-0R010
Toyota	Land Cruiser	2005-2006		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-34020
Toyota	Land Cruiser	2007	Before Aug 2006	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-34020
Toyota	Land Cruiser	2007	After Aug 2006	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Land Cruiser	2008-2018		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Matrix	2007-2013		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Mirai	2016-2017		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
Toyota	Prius	2006-2015		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Prius	2016-2017		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
Toyota	Prius C	2012-2018		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-52020
Toyota	Prius Prime	2017		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-52020
Toyota	Prius V	2012-2016		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Prius V	2017		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-52020
Toyota	RAV 4	2006-2010		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	RAV 4	2011-2012	Non Japan Built	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	RAV 4	2011-2012	Japan Built	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33021
Toyota	RAV 4	2013	Sub Model EV	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	RAV 4	2013-2014	Japan Built	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-52020
Toyota	RAV 4	2013-2017	OEM PN 42607-06020	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
Toyota	RAV 4	2013-2017	OEM PN 42607-0R010	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-52020
Toyota	RAV 4	2004-2005	Indirect TPMS										
Toyota	Sequoia	2004-2007	40deg Steel Wheel	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-0C010
Toyota	Sequoia	2004-2007	20deg Alloy Wheel	31R212		17-20216AK		2	35(4)	315MHz	Yes	Pacific	42607-0C020
Toyota	Sequoia	2008-2017		31R212		17-20217AK		2	35(4)	315MHz	Yes	TRW	42607-0C070
Toyota	Sienna	2006-2018		31R212		17-20217AK		2	35(4)	315MHz	Yes	TRW	42607-0C070
Toyota	Solara	2007-2008		31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Tacoma	2005	Before December: 40deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-0C010
Toyota	Tacoma	2005	Before December: 20deg.	31R212		17-20216AK		2	35(4)	315MHz	Yes	Pacific	42607-0C020
Toyota	Tacoma	2005	After November: 20 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-AD020
Toyota	Tacoma	2005	After November: 40 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-04010
Toyota	Tacoma	2006	After July: 20deg.	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Tacoma	2006	Before August: 20 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-AD020
Toyota	Tacoma	2006	40 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-04010
Toyota	Tacoma	2007-2015	20 deg.	31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Tacoma	2007-2015	40 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-04010
Toyota	Tacoma	2016-2017	Steel Wheel							315MHz	Yes		42607-04020
Toyota	Tacoma	2016-2017	Alloy Wheel							315MHz	Yes		42607-06030
Toyota	Tundra	2005	20 deg.	31R212		17-20216AK		2	35(4)	315MHz	Yes	Pacific	42607-0C020
Toyota	Tundra	2005	40 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-0C010
Toyota	Tundra	2006	Before November: 20 deg.	31R212		17-20216AK		2	35(4)	315MHz	Yes	Pacific	42607-0C020
Toyota	Tundra	2006	Before November: 40 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	Pacific	42607-0C010
Toyota	Tundra	2006	After October: 20deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	TRW	42607-0C050
Toyota	Tundra	2006	After October: 40deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	TRW	42607-0C060
Toyota	Tundra	2007-2011	20 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	TRW	42607-0C050
Toyota	Tundra	2007-2011	40 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	TRW	42607-0C060
Toyota	Tundra	2012-2017	20 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	TRW	42607-0C070
Toyota	Tundra	2012-2017	40 deg.	31R212		17-20217AK		2	35(4)	315MHz	Yes	TRW	42607-08010
Toyota	Venza	2009-2015		31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06011
Toyota	Yaris	2007-2011		31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-33011
Toyota	Yaris	2012		31R213		17-20216AK		2	35(4)	315MHz	Yes	Pacific	42607-0C020
Toyota	Yaris	2013		31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-52020
Toyota	Yaris	2014	Japan Built	31R213		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-52020
Toyota	Yaris	2014	Non Japan Built	31R213		17-20216AK						Pacific	42607-0D010
Toyota	Yaris	2015		31R212		17-20216AK						Pacific	42607-0D010
Toyota	Yaris	2016-2018		31R212		17-20216AK		1	35(4)	315MHz	Yes	Pacific	42607-06020
VOLKSWAGEN													
Volkswagen	Beetle	2007-2011		31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Beetle	2012-2017	Indirect TPMS										-
Volkswagen	CC	2009-2010		31R312		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	CC	2011-2017		31R312	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz		Beru	3AA907275
Volkswagen	EOS	2007-2016		31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	GLI	2008-2010		31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Golf	2010-2011		31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Golf	2012-2017	Indirect TPMS										-
Volkswagen	GTI	2006-2007	w/ Standard Hex Nut	31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D

VEHICLE INFORMATION				SERVICE KIT INFORMATION						SENSOR REPLACEMENT		OEM INFORMATION	
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Volkswagen	GTI	2006-2007	w/ O-Ring Hex Nut	31R311		17-20207AK		4	71(8)	315MHz	Yes	Siemens	1K0-907-253E
Volkswagen	GTI	2008-2012		31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	GTI	2012-2017	Indirect TPMS										
Volkswagen	Jetta	2005-2011		31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Jetta	2012-2017	Indirect TPMS										
Volkswagen	Passat	2006-2008	w/ Standard Hex Nut	31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Passat	2006-2008	w/ O-Ring Hex Nut	31R311		17-20207AK		4	71(8)	315MHz	Yes	Siemens	1K0-907-253E
Volkswagen	Passat	2009-2011		31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Passat	2012-2017	Indirect TPMS										
Volkswagen	Phaeton	2002-2007	433MHz	31R442	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4D0-907-275C
Volkswagen	Phaeton	2002-2007	315MHz	31R442	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	315MHz	Yes	Beru	4D0907275A
Volkswagen	Phaeton	2007	433MHz; After May	31R442	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Volkswagen	Phaeton	2008-2010		31R442	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Volkswagen	Phaeton	2011		31R442	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0907275D
Volkswagen	R32	2008-2010		31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Rabbit	2006-2007	w/ Standard Hex Nut	31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Rabbit	2006-2007	w/ O-Ring Hex Nut	31R311		17-20207AK		4	71(8)	315MHz	Yes	Siemens	1K0-907-253E
Volkswagen	Rabbit	2008-2010		31R311		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Routan	2009-2014		31R312	17-20725AK			5	71(8)	433MHz	Yes	Continental	7B0-907-253A
Volkswagen	Tiguan	2009-2011		31R312		17-20202AK		2	71(8)	315MHz	Yes	Siemens	1K0-907-253D
Volkswagen	Tiguan	2012-2016	Indirect TPMS										
Volkswagen	Touareg	2002-2006		31R443	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	7L0-907-275
Volkswagen	Touareg	2007		31R442	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Volkswagen	Touareg	2007		31R442	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	7L0-907-275
Volkswagen	Touareg	2008-2010		31R442	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0-907-275B
Volkswagen	Touareg	2011-2012		31R443	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4F0907275D
Volkswagen	Touareg	2013-2014		31R443	17-50340, 17-50342, 17-50344, 17-50346			4	35(4)	433MHz	Yes	Beru	4D0-907-275C
Volkswagen	Touareg	2015-2017								433MHz	Yes	Beru	5Q0-907-275B
VOLVO													
Volvo	C30	2007-2013	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	C30	2007-2013	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096-0
Volvo	C70	2006-2007		31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	C70	2008-2013	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	C70	2008-2013	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	S40	2004-2007		31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	30681555
Volvo	S40	2008-2011	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	S40	2008-2011	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	S60	2004-2008		31R310		17-20010AK		2	80(9)	315MHz	Yes	Schrader	31200923
Volvo	S60	2009-2010		31R310			17-20008	2	11.5 (Screw)	315MHz	Yes	Schrader	31200923
Volvo	S60	2011-2013	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	S60	2011-2013	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	S60	2014-2015		31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31341893
Volvo	S60	2015-2016		31R310	17-20725AK	17-20720AK		5	71(8)	433MHz		Continental	31341893
Volvo	S60	2017-2018		31R310	17-20720AK			5	71(8)	433MHz		Continental	31414189
Volvo	S80	2004-2006		31R310		17-20010AK		2	80(9)	315MHz	Yes	Schrader	31200923
Volvo	S80	2007	315MHz	31R310		17-20010AK		2	80(9)	315MHz	Yes	Schrader	31200923
Volvo	S80	2007	433MHz	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	S80	2008-2014	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	S80	2008-2014	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	S80	2015-2016			17-20725AK	17-20720AK		5	71(8)	433MHz		Continental	31341893
Volvo	S90	2016	Indirect TPMS										
Volvo	V50	2005-2007		31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	30681555
Volvo	V50	2008-2012	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096

VEHICLE INFORMATION				SERVICE KIT INFORMATION					SENSOR REPLACEMENT		OEM INFORMATION		
MAKE	MODEL	YEAR	NOTES	Relearn	Valve Kit	Service Kit	Valve Stem	COLOR CODE	Torque In-lbs(N.M)	Supported by Smart Sensor	Supported by Smart Sensor ONE	OEM	OEM PN
Volvo	V50	2008-2012	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	V60	2015-2017		31R310	17-20725AK	17-20720AK		5	71(8)	433MHz		Continental	31341893
Volvo	V70	2004-2007		31R310		17-20010AK		2	80(9)	315MHz	Yes	Schrader	31200923
Volvo	V70	2008-2010	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	V70	2008-2010	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	XC60	2010-2014	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	XC60	2010-2014	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	XC60	2015-2017		31R310	17-20725AK	17-20720AK		5	71(8)	433MHz		Continental	31341893
Volvo	XC70	2004-2007		31R310		17-20010AK		2	80(9)	315MHz	Yes	Schrader	31200923
Volvo	XC70	2008-2012	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	XC70	2008-2012	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	XC70	2013-2014		31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	XC70	2015-2016		31R310	17-20725AK	17-20720AK		5	71(8)	433MHz		Continental	31341893
Volvo	XC90	2004-2007		31R310		17-20010AK		2	80(9)	315MHz	Yes	Schrader	31200923
Volvo	XC90	2008-2012	w/ Siemens Sensor	31R310		17-20201AK		5	80(9)	433MHz	Yes	Siemens	31302096
Volvo	XC90	2008-2012	w/ Continental Sensor	31R310	17-20725AK	17-20720AK		5	71(8)	433MHz	Yes	Continental	31302096
Volvo	XC90	2013-2014		31R310		17-20010AK		2	80(9)	315MHz	Yes	Schrader	31200923
Volvo	XC90	2015-2017		31R310						433MHz		Schrader	50662193
VPG													
VPG	MV-1	2011-2013					17-20018	2	11.5 (screw)	315MHz	Yes	Schrader	9L3Z-1A-189A

Find out more about wheel & tire service tools we have.