










ACHD Installation Guide

Tools Required:	Parts Supplied:
<ul style="list-style-type: none"> • Cross point screw driver • 5/16" nut driver 	<ul style="list-style-type: none"> • Heating element • (6) 5/16" head screws

Electrical Warning: *Prior* to installation, disconnect 115V AC or shut off A/C circuit breaker to prevent electrical shock. There may be a charge on the Capacitor until discharged.

		
<p>1. With the AC on a flat surface, remove outer shroud.</p>	<p>2. Remove evaporator cover.</p>	<p>3. Remove (2) screws that hold evaporator to bulkhead.</p>
		
<p>4. Install mesh screen (reinstall screws from step 3 and add (2) additional screws in locations shown).</p>	<p>5. Install heating element using provided screws.</p>	<p>6. Connect the 3-pin connector to the control box, if installed.</p>
		
<p>7. Secure heater lead with wire holder, as shown.</p>	<p>8. Reinstall evaporator cover.</p>	<p>9. Reinstall shroud.</p>