


Dayco[®] Poly Rib[®] "W" Belt No-Noise Advanced Design



"The #1 Cause for Noise is Misalignment."

- The "W" Profile Rib allows the rib to conform to slight misalignments
- Aramid (Kevlar) noise resistant fibers
- EPDM heat resistant rubber compound for extended life (Kevlar is a registered trademark of DuPont Corporation)

View other replacement engine parts made by Dayco on our website.