


2001 Honda Civic and Acura CL Compressors





There are two compressor options offered for 2001 Honda Civics and Acura CLs. These two options look similar, but are not interchangeable. Usually, the description notes “one wire” or “three wire” in reference to the electrical wiring from the clutch.

In order to determine the correct compressor for the vehicle, take a look at the electrical connection coming from the compressor. Although most of the wires will be covered in protective wrapping, enough wire will be visible to determine if there are one or three wires. Take a look at gpd compressors #6511266 and #6512266 below for reference.

THREE WIRES
gpd #6511266



ONE WIRE
gpd #6512266



When replacing a compressor, it's good practice to replace the drier, expansion valve, and O-Rings.

See gpd Tech Tip #28, “Tips for Better A/C Service” for more information.