



TECHNICAL BULLETIN

NOTICE: Due to the heat the HydraMat might experience during shipping, it may come out of the box in the shape in which it was packaged. To correct this condition, the HydraMat can be laid out in full sun with a little weight on the corners to hold it flat. The heat from the sun will allow the HydraMat to take its original shape. This can also be done with a hairdryer making sure the heat is not held for too long in one spot (DO NOT use a heat gun).