PROBLEM

BULLETIN: 27009



Jeep Cherokee and Grand Cherokee

PROBLEM:

Severe front end vibration/shimmy at moderate highway speeds

- Technicians have reported problems with severe vibration/shimmy from the steering systems of Jeep Cherokee and Jeep Grand Cherokee. The vibrations have been so severe that they transfer into the floor and the steering wheel.
- After checking and/or replacing steering and suspension systems, brakes, wheel bearings, U-joints, wheels, etc., the problem continued. Replacing the steering stabilizer with the OEM replacement did not solve the problem.



STOCK STEERING STABILIZER

Standard bore of 1-5/8" tube diameter 11 or 12mm piston Standard valving

Year	Make/Model	Replacement Part Number
1986-2006 1984-2001 1993-2004	Jeep Wrangler & Comanchee Downsized Jeep Cherokee & Wagoneer Jeep Grand Cherokee	SSD107

SOLUTION:

MOOG[®] Super Trail Boss Steering Stabilizer

 When the technicians replaced the OEM steering stabilizer with MOOG's Super Trail Boss Steering Stabilizer SSD107, the problem disappeared.





SUPER TRAIL BOSS SSD107

Large bore unit with a 2-3/8" tube diameter for better dampening, durability and longer life

14mm piston for higher resistance and better dampening

9.5% stiffer valving in compression and recoil provides better dampening (as measured by a dyno at varying speeds)







Check out the collection of performance suspension parts we offer.