

HOW TO USE:




Step 1:
Lather the surface with generous amount of soap and lather. Loosen any dust or dirt in preparation for Autoscrub Wash Mitt.



Step 2:
Slide Autoscrub across the lubricated paint or glass surface using a back and forth motion with light to medium pressure.



Step 3:
Spray surface clean of soap working form the top down.



Step 1:
Wipe surface dry using a soft micro fiber towel.