

COVERING THE VEHICLES YOU FIX



CONTINUING COVERAGE AND FEATURE IMPROVEMENTS

No tool helps you fix Faster

- **AutoID faster than anybody** – identify CAN vehicles in less than 5 seconds
- Read and clear codes in seconds
- Access top reported code fixes in seconds

Get the most of the 12-month subscription by updating your tool. The latest updates include:

- New USA Domestic / Asian / European vehicle coverage with multiple releases throughout the year.
- Frequent updates to the largest experienced-based solutions available, already with more than 30 million specific fixes.
- Includes performance improvements and repair information.

GENISYS TOUCH & ENCORE FEATURE ENHANCEMENTS


The 3834T TPR Kit

- Bluetooth wireless TPMS
- Sensor ID transfer to Encore or Genisys Touch
- Speeds TPMS registration/relearn
- Eliminates manual entry typos




HD Standard 3895-07 Kit

- Diagnose light, medium- and heavy-duty vehicles
- Includes Class 4 - 8 vehicle coverage



Key & Remote Programming Procedures

Programming and synchronization procedures for vehicle keys and transmitters for remote controlled alarm, central locking and immobilizer systems.



Battery Disconnect Reset Procedures

When and how to reset electrically operated components, accessories and modules for vehicles that have had battery service, replacement or loss of electrical power.

GENISYS TOUCH & ENCORE COVERAGE HIGHLIGHTS

More than 30,000 new vehicle-ECU configurations, 4,500 new systems, 2,500 new bi-directional tests and more since 2014. Examples of new coverage include:

Subaru Transmission coverage 1999-2012, with Actuation and Adjustment tests.

Jaguar Actuation and Adjustment tests.

Land Rover and **Volvo** Actuation and Adjustment tests, including:

- Battery Replacement tests, required on some after replacing the battery.

Cummins diesel engines Injector Kill (All Cylinders) test.

Duramax diesel engines 2006-2014 coverage for Reprogram Injector Flow Rates, required after replacing an injector for GM.

VW/Audi vehicle and system specific tests, such as:

- DTC 01486 ESP Function Test for ABS, EPB Caliper Open and Close tests for PARKING BRAKE (53) and Key FOB Matching for CENTRAL CONVENIENCE (46).

Mercedes Sensotronic Brake systems tests required when replacing the EHB module assembly, including EHB Brake Bleed, EHB Deactivate, EHB Activate.

- Includes new exclusive service instructions for this Bosch system.

Sprinter new coverage for 2011-2013 Model Year vehicles, with Actuation and Adjustment tests.

Ford

- Greatly improved Power Balance & Relative Compression tests.
- Greatly improved Self Diagnostics tests.
- Improvements to Diesel DPF Regeneration Tests.

VW/Audi – new vehicle specific tests, such as:

- HVAC Test, Key FOB Clearing, Key FOB Matching, Key Matching by Immobilizer, DPF Regeneration, Auto Trans Kick-Down, EVAP Purge, EGR, Leak Detection Pump, Reset After DPF Replacement, many more.

BMW

- Battery Exchange Register test added for 2002-2007 7-Series

Jaguar

- Battery Replacement test added for 2009 and newer models

GM

- Failure Records feature added (Touch and Encore)

New Model Year Coverage (in addition to 2014 / 2013 previously released)

- Honda – 2014 MY, Hyundai – 2014 MY, Kia – 2014 MY,
- Nissan – 2014 MY, Mitsubishi – 2014 MY, VW/Audi – 2013 MY

Code-Assist experienced-based update.

Genisys Touch / Encore Subscription Renewal Kit

3895-08 Genisys Touch 12-month diagnostics subscription renewal

3893-LTW Encore 12-month diagnostics subscription renewal

GENISYS TOUCH FEATURES


TECHNICIAN EXPERIENCE IMPROVEMENTS: Scroll Bar

- Implement a scroll bar when more data exists below the screen




TECHNICIAN EXPERIENCE IMPROVEMENTS: Zoom & Favorites in the Browser

- Provide Zoom and end user Favorites functionality within the browser




TECHNICIAN EXPERIENCE IMPROVEMENTS: VCI Self Test

- Ever wonder if a vehicle with a short circuit damaged your Vehicle Communication Interface (VCI) device? A new loopback (self) test for the VCI is now available in the Settings menu.



TECHNICIAN EXPERIENCE IMPROVEMENTS: DataStream Improvements

- Various end user feedback improvements to DataStream.



ENCORE FEATURES

TECHNICIAN EXPERIENCE IMPROVEMENTS:

Home Screen

- All core scan functions available with one button push
- OBD-II Generic can be selected right from the home screen or OEM specific vehicles
- Remove the words "Vehicle Bay" and icon and just say "Select Vehicle"
- Change "Service & Settings" on Home screen tile to say only "Settings"
- Update notifications indicating new version available

TECHNICIAN EXPERIENCE IMPROVEMENTS:

Manual Update

- New Software Update tab with update bubble
- Added check for updates and install update buttons to allow user to check on install
- Specific version available indicated in message area
- Update status provided
- The automatic update is still active, the new manual update gives control to the user

TECHNICIAN EXPERIENCE IMPROVEMENTS:

All System DTC Scan & Automated System Tests

- Faster more robust operation
- See DTC count per system as test runs
- To view DTCs or Test Result during the tests, select the system to see a popup message while the test continues to run.
- Press the Stop button for a report on what has been collected to that point.
- Once the test is complete, press the green arrow for a final report.

TECHNICIAN EXPERIENCE IMPROVEMENTS:

Custom Data Screen on Data Item Group Screen

- Select PIDs individually or by group

