

Operating Instructions for:

6073

Toyota A/C Line Disconnect Tool





CAUTION: To prevent personal injury, wear eye protection that meets ANSI Z87.1 and OSHA standards.

- 1. Rotate the plastic fitting on the air conditioning line to expose the two release holes in the fitting.
- 2. Insert the No. 6073 Disconnect Tool into the holes, and push on the tool to release the fitting so it can be opened.

