



Upper Door Skin Set Installation Instructions

Part #: DS100XX and DS101XX
1987-2006 YJ and TJ Wrangler

-Read all instructions carefully prior to starting installation.

-We recommend installing these skins in temperatures 70F (21C) and above. This will make installation easier and reduce the risk of damaging the skins. Laying all of the pieces in the sun is also suggested to ease installation.

-Do not over-stress the zippers or material. Failure to comply may damage components.

Kit Contents:

2 - Door Skins



1. Begin by removing the upper door from the vehicle. Remove the door skin from the frame. If an OE door skin is being removed it will need to be cut off.
2. Un-zip the window on replacement skin to help ease installation.
3. Install the replacement door skin onto the frame in the order shown to the right.

TJ Wrangler models: Follow Figure 1

YJ Wrangler models: Follow Figure 2

NOTE: It may be necessary to roll the corner of the door skin onto the frame with a pry tool. Do not over-stress the fabric of the skin. Damage may occur.

4. Once the skin is installed, make any adjustment necessary so the skin fits properly. Affix the hook and loop fasteners. Fully zip the window.
5. Reinstall the upper door on the vehicle. Make any adjustments necessary for an ideal fitment.



NOTE: The skins may seem wrinkled when first installed; this is caused by the fabric becoming wrinkled during shipping. It will relax after a few days on the vehicle.

NOTE: Over the years many different companies have produced upper door frames. While they are similar, the exact dimensions will vary which may require additional adjustments in installation.

WARNING

This product is designed to enhance the appearance of the vehicle and only for protection against the elements. Do not rely on this product to contain occupants within the vehicle or to protect against injury during an accident.

While every attempt is made to ensure that the information contained in these instructions is correct, no liability can be accepted by the authors for loss, damage, or injury caused by any errors in, or omissions from the information given. All service should be performed by qualified mechanics. Crown Automotive Sales Co., Inc. cannot be held responsible for any mechanical work performed. Standard and accepted safety precautions should be used in every procedure.