



SPYDER™

SKU# 5002181



SCAN THE QR CODE TO
VIEW THE INSTALL VIDEO

PACKAGE CONTENTS:



• 2X TAIL LIGHT ASSEMBLIES

FITMENT:

• 2002-2009 CHEVROLET TRAILBLAZER

-  [FACEBOOK.COM/SPYDERAUTO](https://facebook.com/spyderauto)
-  [LINKEDIN.COM/COMPANY/SPYDER-AUTO](https://linkedin.com/company/spyder-auto)
-  [INSTAGRAM.COM/SPYDERAUTO](https://instagram.com/spyderauto)
-  [TWITTER.COM/SPYDERAUTO](https://twitter.com/spyderauto)
-  [TIKTOK.COM/@SPYDERAUTO](https://tiktok.com/@spyderauto)



SCAN THE QR CODE
TO VISIT OUR WEBSITE

WARNING: BY READING THIS DOCUMENT, YOU AGREE IT IS ONLY TO BE USED AS AN EDUCATIONAL GUIDE. SPYDER AUTO NOR ITS DEALERS MAKE GUARANTEES ON ANY FINISHED RESULTS, NOR ARE THEY TO BE HELD RESPONSIBLE FOR ANY DAMAGE, MISUSE, OR PERSONAL INJURIES. IF YOU ARE UNABLE TO CLEARLY UNDERSTAND AND ADAPT THE INFORMATION BELOW, PROFESSIONAL INSTALLATION IS RECOMMENDED. FOR ANY ISSUES OR QUESTIONS ABOUT YOUR SPYDER PRODUCT, REACH OUT TO OUR TECH SUPPORT TEAM TECHSUPPORT@SPYDERAUTO.COM. IT IS THE INSTALLER'S RESPONSIBILITY TO CONFIRM COMPLIANCE WITH STATE AND LOCAL LAWS. THIS PRODUCT CAN EXPOSE YOU TO CHEMICALS INCLUDING CHROMIUM (HEXAVALENT COMPOUNDS), WHICH ARE KNOWN TO THE STATE OF CALIFORNIA TO CAUSE CANCER AND BIRTH DEFECTS OR OTHER REPRODUCTIVE HARM. FOR MORE INFORMATION GO TO WWW.P65WARNING.CA.GOV

TOOLS REQUIRED:

- PHILLIPS SCREWDRIVER



STEP 1:

DISCONNECT THE NEGATIVE BATTERY TERMINAL



STEP 2:

REMOVE (2) PHILLIPS SCREWS SECURING THE TAIL LIGHT




STEP 3:


UNSEAT THE TAIL LIGHT AND DISCONNECT THE HARNESS



STEP 4:
REMOVE (3) PHILLIPS SCREWS SECURING THE BULB BAR



STEP 5:
REMOVE (2) BULBS FROM THE BULB BAR
(NOTE: NEVER TOUCH BULBS WITH BARE HANDS)



STEP 6:

CONNECT SOCKET INSERT TO BULB SOCKET BAR MAKING SURE THE BLACK SIDE OF WIRE IS ON THE BOTTOM



STEP 7:

INSTALL SOCKET BAR ONTO SPYDER TAIL LIGHT AND REINSTALL THE (3) PHILLIPS SCREWS



STEP 8:
RECONNECT THE WIRE HARNESS



STEP 9:
SEAT THE SPYDER TAIL LIGHT AND REINSTALL THE (2) PHILLIPS SCREWS SECURING THE TAIL LIGHT



STEP 10:

RECONNECT THE BATTERY AND TEST THE FUNCTIONS TO ENSURE THEY FUNCTION PROPERLY