

# TYC™

## CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

**TYC #: 800002C**

Replacement for OEM  
999M1-VS251

**03-08 Infiniti FX-35/ FX-45**

03-07 Infiniti G35 Coupe

03-06 Infiniti G35 Sedan

Estimated Time : 20 min.

02-06 Nissan Altima

04-08 Nissan Maxima

03-07 Nissan Murano

00-06 Nissan Sentra (OP)



1. The filter is located behind the glove compartment. Remove the 4 screws along the top of the glove box.

2. Remove black panel by pulling down to release from fasteners. Set panel aside.



3. Remove retaining bolt by turning counter-clockwise, then pull kick-panel to the left to remove.

4. Remove the 2 remaining screws holding up the glove box on each side.



5. With all the retaining screws removed, pull down the entire glove box. Disconnect the white and yellow connectors to gain access to the filter housing.



6. Push on the tab at the right of the filter access door, then pull door to the right to remove. Set access door aside.



7. Slide out old filter from housing, replace with new TYC filter.

8. Reinstall in reverse order.

Installation guide pictures are from the **BOLD** vehicle model. \*OP = Cabin Air Filter is an OPTION on this application. Some vehicles may not come equipped with a Cabin Air Filter.