


- Cleaner Air for Passengers
- Enhanced HVAC Performance
- Easy Installation, Perfect Fit

TYC #: 800007C

Estimated Time: 5 min.

Replacement for OEM XS4Z 19N619 AA (Particle) XS4Z 19N619 CA (Combination)





1. The filter is located in the engine bay, under the windshield on the passenger side. Locate the 3 clips holding the plastic cover in place and remove cover.



3. Insert <u>new TYC filter</u> into the space where the cover used to be. Ensure that the Air Flow arrow is pointing down.

Note: The filter will replace the removed filter cover. The removed filter cover will not be reinstalled.

4. Reinstall the plastic cover in reverse order.



2. Release filter cover by pulling on the 2 locking tabs. Remove filter cover.