

TYC™

CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit


TYC #: 800025P

Estimated Time : 5 min.

Replacement for OEM
87139-52020 (OLD)
87139-02090 (NEW)

08-10 Scion xB
08-10 Scion xD
09-10 Toyota Corolla

08-10 Toyota Highlander
06-10 Toyota RAV 4
07-10 Toyota Yaris



1. The filter is located behind the glove compartment. Open glove box and push in on the sides while pulling down to disengage the latches.



3. Push on the retaining tab to release the filter access door. Remove door and set aside.

4. Slide out old filter*, replace with new TYC filter into cavity, ensuring that the Air Flow arrow is pointing down.



2. Locate retaining arm on the bottom right of glove box, pull arm towards the right to release. Allow glove box to swing down on its hinges, exposing the filter access door behind it.



5. Reinstall in reverse order.

*Note: not all vehicles come equipped with a filter. If there is no filter present, simply insert new TYC filter.

Installation guide pictures are from the **BOLD** vehicle model.

Discover other A/C and heating parts on our website.