

TYC™

CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800029P

Estimated Time : 5 min.

Replacement for OEM
97133-2E210
08790-2E200-A

05-05 Hyundai Tucson (w/ Auto AC)

06-10 Kia Rio (Sedan/Hatchback) 10-10 Hyundai Genesis

05-10 Kia Sportage

10-10 Kia Forte

07-10 Kia Rondo

10-10 Kia Sorento



1. The filter is located behind the glove compartment. Open the glove box and remove the latches on each side by pushing them inwards. Remove the black retaining string that holds up the glove box.



3. Remove old filter and replace with new TYC filter into filter frame, slide frame back into position. Ensure that Air Flow arrow is pointing down.



2. Let the glove box swing down on its hinges to expose the filter access door behind it. Push on the locking tabs to release the filter access door and slide out the filter frame.

4. Reinstall in reverse order.

Note: Not all models come equipped with cabin air filters pre-installed in the filter frame. If yours is empty, remove the empty frame and install new filter into it.

Installation guide pictures are from the **BOLD** vehicle model.