

# TYC™

## CABIN AIR FILTER


- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

**TYC #: 800030P**

Estimated Time : 10 min.

Replacement for OEM  
97133-2D000  
97133-2D100  
08790-2D000-A

01-06 Hyundai Elantra  
07-08 Hyundai Entourage  
**03-08 Hyundai Tiburon**  
06-10 Kia Sedona



1. The filter is located behind the glove compartment. Remove glove compartment by removing the 5 screws securing it in place, and pushing the entire compartment down to free it from its mounting clips.



3. Slide out old filter (if present\*) and replace with new TYC filter. Ensure that Air Flow arrow is pointing down.

4. Reinstall in reverse order.



2. Remove the filter access door by pushing up on the 2 retaining tabs. Remove filter access door and set aside.

\*Note: Some vehicles may not have the filter pre-installed. If there is no filter in your vehicle, simply insert the new filter into the empty cavity.

Installation guide pictures are from the **BOLD** vehicle model.