


TYC #: 800042P

Cleaner Air for Passengers
Enhanced HVAC Performance
Easy Installation, Perfect Fit

Estimated Time : 5 min.


Replacement for OEM 87139-YZZ05

00-04 Toyota Avalon



1. The filter is located behind the glove compartment. Remove the latches by pushing them inwards. Remove the damping mechanism at the right side of the glove box door. Allow glove box to swing down on its hinges, then remove glove box by pulling it out.

2. Remove the 3 screws holding up the back of the glove compartment. Pull down on the entire cover to free it from it's mounting pins. Set cover aside.



3. Push on the 2 retaining tabs to release the filter access door. Slide out the filter frame, replace old filter with <u>new TYC filter</u>, making sure Air Flow arrow is pointing down.

4. Reinstall in reverse order.