

TYC™

CABIN AIR FILTER

- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800095P

Estimated Time : 5 min.

Replacement for OEM
EG21-61-P11

07-10 Mazda CX-7




1. The filter is located behind the glove compartment. Open glove box and push in on the sides to clear the latches. Allow box to swing down on its hinges.



3. Slide out the old filter to remove; replace with new TYC filter. Ensure that the air flow arrow is pointing down.

4. Reinstall in reverse order.



2. Pull on the retaining tab on the filter access door to loosen it. Remove door and set it aside.