

TYC™

CABIN AIR FILTER


- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800097P

Replacement for OEM
95861-54J00

Estimated Time : 15 min.

03-05 Suzuki Grand Vitar
03-05 Suzuki XL-7



1. The filter is located behind the glove compartment. Push in on the sides of the glove box to clear the retaining latches.



3. Pull up on the two tabs holding the filter access door. Remove door and set aside.



2. Disconnect the damping arm found at the right side by removing the screw. Allow glove box to swing down on its hinges, exposing the filter access door.



4. Grab on the filter frame and slide it out of the cavity.

5. Reinstall in reverse order. Make sure that the Up arrow is pointing up.

Installation guide pictures are from the **BOLD** vehicle model.

Discover other A/C and heating parts on our website.