

# TYC™

## CABIN AIR FILTER


- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

**TYC #: 800123P**


Estimated Time : 5 min.

Replacement for OEM  
95860-80J00


### 07-10 Suzuki SX4 Sedan & Hatchback



1. The filter is located behind the glove compartment. Push in on the sides of the glove box latches while pulling down to clear the latches. Allow the glove box to swing down on its hinges.



2. The filter will become visible after the glove box swings down. Reach in and using both hands, pinch the plastic tabs towards each other while pulling backwards to release the filter.



3. Slide the entire filter out from its housing to remove.

4. Install new TYC filter by inserting it into the housing. Ensure that the “Up” arrow is pointing upwards.

5. Reinstall in reverse order.

Installation guide pictures are from the **BOLD** vehicle model.

Looking for replacement A/C and heating parts? Visit our website.