

TYC™

CABIN AIR FILTER


- ▶ Cleaner Air for Passengers
- ▶ Enhanced HVAC Performance
- ▶ Easy Installation, Perfect Fit

TYC #: 800148C


Replacement for OEM
C2Z6525

Estimated Time : 5 min.


09-10 Jaguar XF



1. The filter is located below the glove compartment. Remove the 2 retaining pins and pull the entire black plastic cover downwards. Set plastic cover aside.



2. The filter access door is located at the upper right corner. Push in on the retaining tabs on each side of the access door to release it. Set access door aside.



3. Pull down the filter access door to remove the old filter.

4. Install new TYC filter onto access door. Ensure that the air flow arrow is pointing towards the inside of the cabin.

5. Reinstall in reverse order.