

REMANUFACTURED AIR STRUT SERVICE BULLETIN



ATTENTION




UPON VISUAL INSPECTION OF YOUR AIR STRUT, IT MAY APPEAR THAT THE AIR STRUT IS BENT. THIS IS COMPLETELY NORMAL AND THE AIR STRUT WILL STRAIGHTEN OUT WHEN PROPERLY INSTALLED ON THE VEHICLE.

DO NOT RETURN AIR STRUT DUE TO THE VISUAL APPEARANCE OF IT BEING BENT.



THIS IS NORMAL
(AS-2193)



THIS IS NORMAL
(AS-2540, AS-2547, AS-2548, AS-2603, AS-2604)



THIS IS NORMAL
(AS-3360, AS-3361, AS-3366, AS-3367, AS-3358, AS-3359)

Arnott® is committed to the quality of its products.